## UNITED STATES DISTRICT COURT NORTHERN DISTRICT OF TEXAS DALLAS DIVISION

UNITED STATES OF AMERICA,

Plaintiff, : No. 3:11-CV-00116-F

v.

RANGE PRODUCTION COMPANY, a Delaware Corporation; and RANGE RESOURCES CORPORATION, a Delaware Corporation,

Defendants.

## APPENDIX IN SUPPORT OF UNITED STATES' MEMORANDUM IN OPPOSITION TO DEFENDANTS' MOTION TO DISMISS

#### TO THE HONORABLE JUDGE OF THE COURT:

Plaintiff, the United States of America files this Appendix in Support of its Memorandum in Opposition to Defendants' Motion to Dismiss. The Appendix contains true and correct copies of the following described and indexed documents including excerpts of the Administrative Record:

### **INDEX**

<u>Document</u>	Page No.
Certification of Index to Administrative Record	1
Administrative Record Index	2-3
Railroad Commission of Texas, Initial Report, dated Aug. 20, 2010	4-5
Railroad Commission of Texas, Status Report, dated Sept. 22, 2010	6-47
Railroad Commission of Texas, Status Report, dated Nov. 5, 2010	48-49

State of Texas Well Report for Lipske [sic] domestic water well ("Domestic Well 1")	50-51
State of Texas Well Report for Godfrey/Hayley domestic water well ("Domestic Well 2")	52
State of Texas Well Reports for Hurst domestic water wells	53-58
Ron Van Wyk Record of Communication, dated Aug. 17, 2010	59
Ron Van Wyk Record of Communication, dated Aug. 19, 2010	60
Email from Willie Lane, Chief, Water Resources Section, EPA, dated Aug. 20, 2010	61
Railroad Commission of Texas, Notice of Hearing, dated Dec. 8, 2010	62-66
Email from John A. Riley (Counsel for Range) to Suzanne Murray (Regional Counsel for EPA Region 6), dated Dec. 9, 2010	67-68

## Respectfully submitted,

IGNACIA S. MORENO Assistant Attorney General Environment and Natural Resources Division U.S. Department of Justice

Dated: May 9, 2011 s/ Keith T. Tashima

JEFFREY K. SANDS
Senior Attorney
Maryland State Bar No. 199412150130

KEITH T. TASHIMA Trial Attorney

New York State Bar No. 3938701

BRADLEY L. LEVINE

Trial Attorney

District of Columbia Bar No. 974925 Environmental Enforcement Section

Environment and Natural Resources Division

U.S. Department of Justice

P.O. Box 7611 Ben Franklin Station

Washington, DC 20044-7611 (202) 514-3908 (Sands)

(202) 616-9643 (Tashima)

(202) 514-1516 (Levine) (202) 616-2427 (fax) jeffrey.sands@usdoj.gov keith.tashima@usdoj.gov bradley.levine@usdoj.gov

JAMES T. JACKS UNITED STATES ATTORNEY

LYNETTE WILSON
Assistant United States Attorney
1100 Commerce Street, Suite 300
Dallas, TX 75242
(214) 659-8911
lynette.wilson@usdoj.gov

## OF COUNSEL:

SCOTT McDONALD
Chief, Water Enforcement Branch
TUCKER HENSON
Assistant Regional Counsel, Water Enforcement Branch
Office of Regional Counsel
U.S. Environmental Protection Agency, Region VI
1445 Ross Avenue, Suite 1200
Dallas, TX 75202
(214) 665-2718 (McDonald)
(214) 665-8148 (Henson)

# APPENDIX IN SUPPORT OF UNITED STATES' MEMORANDUM IN OPPOSITION TO DEFENDANTS' MOTION TO DISMISS

EXCERPTS FROM EPA ADMINISTRATIVE RECORD

## IN THE UNITED STATES DISTRICT COURT FOR THE NORTHERN DISTRICT OF TEXAS

UNITED STATES ENVIRONMENTAL	)	
PROTECTION AGENCY	)	
Plaintiffs,		
v.	) Civil Action No.	
RANGE RESOURCES CORPORATION and RANGE PRODUCTION COMPANY	)	
Defendants.	) ) )	

## CERTIFICATION OF INDEX TO ADMINISTRATIVE RECORD

I, Jerry Saunders, am the Associate Director of the Water Enforcement Branch, Office of Compliance and Enforcement Division, U.S. Environmental Protection Agency, Region 6.

I am the custodian of the administrative record of the agency decision under review in the above-captioned matter.

I certify that the attached is a true and correct index of the administrative record pertaining to the agency decision under review.

I swear under penalty of perjury that the foregoing is true and correct.

Date: January 13, 2011

Document	Date of	72.5
Identification	Document	Document Description
		Summary of Gas Analyses Dom1, Range Butler 1-H, summary of water analyses
1	12/8/2010	Dom1, Dom2, Range Butler 1-H, graph of Dom1-Butler 1-H isotope data (3 p).
		Cover letter and results of Isotech analysis Dom1, Range Butler 1-H, graph of
. 2	11/3-30/2010	isotope data - 11/30/2010 (3p).
3		Water test results for EPA samples Dom1, Dom2, Range Butler 1-H (54 pp).
4	9/17/2010	Sampling and QA Project Plan (6 pp).
5		EPA Region 6 Site Safety Plan (15 pp).
		Summary of air monitoring, Wolf Eagle Environmental for Steve Lipsky (Air -
6	8/18/2010	Summary_outside well_indoor bathroom.pdf) (3 p).
7		Results of air monitoring Outside by Well, Wolf Eagle Environmental for Steven
8		Results of air monitoring Master Bathroom, Wolf Eagle Environmental for Steven
		Well Water Laboratory Test Results Methane, Ethane, Ethene, Wolf Eagle
9	8/10/2010	Environmental for Steven Lipsky well (Water - Methane_Ethane_Ethene.pdf) (11
	0.1.0.2010	Well Water Laboratory Test Results VOC and MTBE, RCRA 8 Metals, ICP MS
		Metals Ion Chromograph, ph EPA 9040 conducted for Wolf Eagle Environmental
10	8/10/2010	for Steven Lipsky well (Water - VOC_MTBE_Metals_lon_pH-1.pdf, Water -
10	O/ TO/EOTO	American Radiation Services, Inc. Laboratory Analysis Report for Wolf Eagle
11	9/10/2010	Environmental for Steven Lipsky well (Water-Radiation.pdf) (8 pp).
- ' '	0/10/2010	Well Water Laboratory Test Rsults, Surfactants - MBAs & CTAs, Steve Lipsky
12	8/14/2010	well (Water-Surfactants.pdf) (8 pp).
12	0/14/2010	Report, Comprehensive Well Water Analysis, Hayley well, September 2010; Wolf
13	Sep. 10	Eagle Environmental (Hayley final water report pdf (4 pp).
	Oep-10	Anachem Inc. for Wolf Eagle Environmental, Analytical Report, Volatiles and
14	0/2/2010	
17	9/2/2010	MTBE, Xenco Lab report, MBAS report, Hayley well (Hayley water labs.pdf) (47
15	0/2/2010	Anachem Inc. for Wolf Eagle Environmental, Analytical Report, Hayley well (HayleyAna26Aug.pdf) (26 pp).
	91212010	
16	0/2/2010	Analytical Report 387479 for Wolf Eagle Environmental, Xenco Laboratories,
10		methane, ethane, ethene Hayley well (HayleyXen26Aug.pdf) (11 pp).
17		Armstrong Forensic Laboratory for Wolf Eagle Environmental, MBAS test, Hayley
		well (HayleyLabArm26Aug.pdf) (8 pp).
18		RRC of Texas Initial Report, Lispky, Steve Complaint No. 7B-9601 (2 pp).
40		RRC of Texas Status Report, Lispky, Steve Complaint No. 7B-9601 gas and
19	9/22/2010	water sample results, analysis (42 pp).
00	44/5/0040	RRC of Texas Status Report, Lispky, Steve Complaint No. 7B-9601, summary of
20		10/14/2010 and 10/26/2010 inspections (2 pp).
21		Well Data for Range Butler Unit Well 1-H, RRC of Texas online data (36 pp).
22		Well Data for Range Teal Unit Well 1-H, RRC of Texas online data (39 pp).
22		Well Data for Devon Durant South Unit Well 1-H, RRC of Texas online data (34
23	11/2010	<u> </u>
24		Well Data Lake Country Acres (19 pp).
25		Well Data Domestic Wells in the area (61 pp).
	1	Source Identification of Stray Gases By Geochemical Fingerprinting, Dennis D.
		Coleman, Isotech Laboratories, Inc., Champaign, Illinois, USA. Solution Mining
26		Research Institute: Spring 2004 Technical Meeting, Wichita, Kansas, USA 18-21
		Advances in the Use of Geochemical Fingerprinting for Gas Identification, Dennis
		D. Coleman, Isotech Laboratories, Inc. Champaign, Illinois, American Gas
27	5/9/1994	Association Operations Conference, May 9-11, 1994 (pp 10).

		SPE 26171, Isotope Analyses of Gases in Gas Field and Gas Storage
		Operations, Martin Schoell and P.D. Jenden, Chevron Petroleum Technology Co.;
		M.A. Beeunas, Chevron U.S.A. Production Co.; and D.D. Coleman, Isotech
28	6/28/1993	Laboratories Inc., SPE Gas Technology Symposium, Calgary, Alberta, Canada,
		SPE 15586, Huntsman and West Engelland Fields, Cheyenne County, Nebraska:
		A Case History of Technical Lessons From a Legal Conflict, M.R. Tek, U. of New
		South Wales, D. D. Coleman, Consulting Geochemist, and J.M. Parker,
		Consulting Geochemist, 61st Annual Technical Conference and Exhibition of the
29	10/5/1986	Society of Petroleum Engineers held in new Orleans, LA October 5-8, 1986 (16
		Geochemical Fingerprinting: Identification of Storage Gas Using Chemical and
		Isotopic Analyses, Dennis D. Coleman, Isotech Laboratories, Inc. NATO
	1	Advanced Studies Institute on Underground Storage of natural Gas - Theory and
30	5/2/1988	Practice, Ankara, Turkey, May 2-13, 1988 (14 pp).
		Isotopic Identification of Leakage Gas From Underground Storage Reservoirs - A
		Progress Report, Dennis D. Colemant, Wayne F. Meents, Chao-Li Liu, Robert A.
31	1977	Keogh, Illinois State Geological Survey, 1977 (12 pp).
32	1/12/2011	Declaration of Chris Lister, EPA (January 12, 2011)
. 33	12/2/2010	Letter from David T. Ritter to Scott Mcdonald, EPA (December 2, 2010)
34	1/12/2011	Declaration of Jerry Saunders, EPA (January 12, 2011)
35	12/3/2010	Email between Al Armendariz, EPA, and Victor Carrillo, TRRC (December 3,
36	11/23/2010	Email from Chris Lister, EPA to James Allman, TRRC (November 23, 2010)
		Emails between Chris Lister and Officials at the Texas Railroad Commission
37	10/21-12/03/10	(October 21, 2010 through December 3, 2010)
38	8/17/2010	Record of Communication between Ron Van Wyk and Doug Allmond, TRRC
39	8/19/2010	Record of Communication between Ron Van Wyk and Steve Lipsky (October 19,
		Email from Willie Lane, EPA, to Stephen Gilrein, Jerry Saunders and David
40	8/20/2010	Garcia, EPA (August 20, 2010)
41	11/28/2010	Email from Doug Beak, EPA, to Chris Lister, EPA (November 28, 2010)
42	12/2/2010	Email from Jerry Saunders to John Blevins and Stephen Gilrein, EPA (December

Victor G. Carrillo, Chairman Elizabeth A. Jones, Commissioner Michael L. Williams, Commissioner



RAMON FERNANDEZ JR., P.E.
ACTING DEPUTY DIRECTOR, OIL AND GAS DIVISION
D. W. -JOE- CRESS
DISTRICT DIRECTOR

## RAILROAD COMMISSION OF TEXAS

## OIL AND GAS DIVISION

August 20, 2010

Unidentified

## **INITIAL REPORT**

Lipsky, Steve Complaint No. 7B-9601 Lipsky Property Lease Domestic Water Well Parker County, Texas Job No. 10-8443

On August 6, 2010, Railroad Commission of Texas District 7B Office was contacted by Steve Lipsky concerning operations on the subject property. Steve Lipsky's concern was natural gas in a water well. On August 6, 10, 11 and 17, 2010, inspections of the property were conducted by Randy Hobbs and Bubba Jonas. During the inspections, the following were observed:

SWR 8: The Lipsky property water well was drilled on July 4, 2005, by Pecks Well Service to a depth of 200. No other completion data for the water well was available at the time of this report. The well is located 200 feet north of the residence (GPS N32.56312 W97.79144), and 500 yards east of the Brazos River. The water well produces a sustained rate of 10 gallons/minute and will pump down within 15 minutes. Well water is pumped from the wellhead to a 5,000 gallon open top plastic tank inside a building approximately 10 feet east of the water well. Well water in the tank is circulated by two ozonator pumps to remove residual sulfur odor that has been present since the well was drilled. Water from the tank is pumped into a pressurized water system servicing the residence and property. The property utilizes approximately 1,500 gallons of water per day. The complainant stated that on or about the week of July 26, 2010, gas in the water well was evident while replacing a submersible pump. During the inspection, a gas odor was detected from the water. No abnormal visual characteristics were noted and a field test for chlorides was less than 100 mg/L.

On August 10, 2010, a joint inspection of the property was conducted by Bubba Jonas and Steve Lipsky, Bubba Jonas conducted a ¼ mile radius inspection of oil and gas production. Range Production Company (691703) operates two gas wells that terminate within the ¼ mile radius. The Teal Unit Lease (253779), Well No. 1H and Butler Unit Lease (253732), Well No. 1H have bottom hole depths of 5,866 and 5,852 feet true vertical depth respectively. The surface location of the two gas wells is located 2,240 feet southeast of the referenced water well. Inspection of the leases surface location found the Butler Unit, Well No. 1 to have 30 psig of bradenhead pressure. The bradenhead would blow dry gas with the valve in the open position. The operator was contacted to take corrective action to address the bradenhead pressure. No other active wells are located within a half-mile radius of the referenced water well.

On August 11, 2010, a joint inspection of the property was conducted by Bubba Jonas; Steve Lipsky; Alisha Rich, Wolf Eagle Environmental; Dan Long and Ryan Albert, TCEQ; and Shawn Scott, Parker County Fire Marshall. Gas was apparent in the casing of the water well. Bubba Jonas collected water samples for analysis by the Commission's contracted lab (Anacon Lab).

Range Resources Corp.

Docket: SDWA-06-2011-1208

Page 2 Lipsky, Steve Complaint 7B-9601 Unidentified Lipsky Property Lease Parker County, Texas August 20, 2010

On August 17, 2010, a joint inspection of the property was conducted by Bubba Jonas and Steve Lipsky. Water samples collected on August 11, 2010, were received by Anacon outside acceptable temperature requirements. Subsequent water samples taken from the water well during this inspection were received by Anacon Lab on August 18, 2010. Analysis of the water samples is pending.

Reinspection is scheduled for the week of August 30, 2010, to monitor the status of the water well. Upon receipt and review of the analytical results of the water well water samples further Commission action may be taken. Please direct any questions with regard to this complaint to Doug Alimand at (325) 677-3545.

Sincerely.

Doug Allmand Engineering Specialist

DA/mm

Assistant District Director

District Director

cc: Field Operations, RRC, Austin

Steve Lipsky 127 River Oak Court Weatherford, TX 76087

Sid Siocum, Water Section Manager Texas Commission on Environmental Quality 2309 Gravel Drive Fort Worth, TX 76118

Ron VanWyk, Water Enforcement Branch Environmental Protection Agency 1445 Ross Avenue Dallas, TX 75202

Range Production Company (691703) 100 Throckmorton St Ste 1200 Fort Worth, TX 76102 VICTOR G. CARRILLO, CHAIRMAN ELIZABETH A. JONES, COMMISSIONER MICHAEL L. WILLIAMS, COMMISSIONER



RAMON FERNANDEZ JR., P.E.
ACTING DEPUTY DIRECTOR, OIL AND GAS DIVISION
D. W. -JOE- CRESS
DISTRICT DIRECTOR

## RAILROAD COMMISSION OF TEXAS

## OIL AND GAS DIVISION

September 22, 2010

Unidentified

#### STATUS REPORT

Lipsky, Steve Complaint No. 7B-9601 Lipsky Property Domestic Water Well Parker County, Texas Job No. 10-8443

Steve Lipsky's concern was natural gas in a water well. On August 26, 2010, a joint inspection of the property was conducted by Bubba Jonas, Doug Allmand, Steve Lipsky, Shyla Lipsky, Alisa Rich, David Ritter and Bryn Meredith. On September 21, 2010, a file review was conducted by the District Office. During the inspection and file review, the following were observed:

SWR 8: The Lipsky property water well was previously reported as drilled on 7/4/05, however, well records obtained from Pecks Well Service on 9/20/10, indicate drilling started and was completed on 4/11/05. An air rotary rig was used to drill a 7 inch well bore to a depth of 200 feet. A 4 inch slotted plastic casing was set from 180 feet to 200. Solid plastic 4 inch casing was run from surface to 180 feet with a steel sleeve surface completion. The casing was gravel packed from 60 to 200 feet and cemented from surface to 60 feet. The static water level was at 65 feet with a submersible pump set at 180 feet. The pump yielded 18 gpm with 90 feet of drawn down after 3 hours. The water well completion report described the water quality as good. Chemical analysis was not conducted at the time of completion and no know strata was penetrated which would contain undesirable constituents. Lithology of the water well is contained in the attachment State of Texas Well Report for Tracking #108518.

On August 26, 2010, a joint inspection of the property was conducted by Bubba Jonas, Doug Allmand, Steve Lipsky, Shyla Lipsky, Alisa Rich, David Ritter and Bryn Meredith. Two gas samples were obtained from the water well casing head during the inspection. The gas samples were shipped to the Commission's contracted lab (Anacon Lab) for TCD/FID analysis.

Range Production Company (691703) provided comparative analysis from the production tubing and bradenhead gas taken at the Butler Unit Lease (253732) Well No. 1 H. Each of the three gas samples taken, the Lipsky water well, the Butler Unit production and the Butler Unit bradenhead gas had distinct characteristics from each of the others. Gas analysis from the Butler production tubing was collected on 2/16/10. The operator was requested to resample the produced and bradenhead gas at the Butler Unit Well No. 1 H to obtain current comparative data. Complete gas analysis for each of the three locations sampled are attached.

Water samples taken on 8/17/10 from the Lipsky water well were analyzed for TPH, BTEX and chemical properties. TPH was not detectable at reporting limits. BTEX analysis detected Benzene at 0.00864 mg/L and Toluene at .00612 mg/L. The threshold limit for a Class 1 groundwater resource for Benzene is 0.005 mg/L and Toluene is 1.0 mg/L. Ethylbenzene and Xylenes were not detectable at reporting limits. Star diagrams, a pictorial representation of chemical analyses, were performed by the laboratory. Copies of those are enclosed along with some examples of representative star diagrams obtained from the The Texas Department of Water Resources, Report 269, "Occurrence, Availability, and Chemical Quality of Ground Water in the Cretaceous Aquifers of North-Central Texas, April 1982".

Docket: SDWA-06-2011-1208 Administrative Record #19

Range Resources Corp.

3444 NORTH I<sup>ST</sup> \* SUITE 600 \* ABILENE, TEXAS 79603 \* PHONE: 325/677-3545 \* FAX: 325/677-7122 TDD 800/735-2989 OR TDY 512/463-7284 AN EQUAL OPPORTUNITY EMPLOYER

000251 Pl. Appx. 000006 Page 2 Lipsky, Steve Complaint 7B-9601 Unidentified Lipsky Property Parker County, Texas September 22, 2010

According to the RRC Field Operations Manual, A Na/Cl of < 0.60 and a Cl/SO<sub>4</sub> ratio > 10.0, are indicators of contamination by oilfield brine. Chemical analyses of the Lipsky water well samples indicated a Na/Cl of 10 and Cl/SO<sub>4</sub> of 34. The star diagram indicates samples of the Lipsky water well are native groundwater, however the ionic ratios are inconclusive as to whether the well water is contaminated with oilfield brine. The Lipsky water well had a chloride concentration of 24 mg/L, total dissolved solids were 646 mg/L and a pH of 8.83.

In addition to obtaining current gas samples for analysis from the Butler Unit Well No. 1H, the operator has been directed to pressure test the production casing from a point below the top of cement behind the production casing. The operator submitted a proposal to the District Office and the test date is pending. After receiving the results of the pressure test further Commission action may be taken.

File review is scheduled for the week of October 25, 2010. Monthly inspections are scheduled to monitor the status of the Lipsky water well. The District Office is currently conducting a geologic assessment of the area and evaluating data from adjacent well records. Please direct any questions with regard to this complaint to Doug Allmand at (325) 677-3545.

Sincerely,

Doug Allmand

**Engineering Specialist** 

Allmad

**DA/mm** 

☐ Assistant District Director

District Director

cc: Field Operations, RRC, Austin

Steve Lipsky 127 River Oak Court Weatherford, TX 76087

Sid Slocum, Water Section Manager Texas Commission on Environmental Quality 2309 Gravel Drive Fort Worth, TX 76118

Ron VanWyk, Water Enforcement Branch Environmental Protection Agency 1445 Ross Avenue Dallas, TX 75202

Range Production Company (691703) 100 Throckmorton St Ste 1200 Fort Worth, TX 76102

RAILROAD COMMISSION OF TEXAS			•	D-O
Oil and Gas Division	District (	Office		rev. 6/07
Compliance Section	INSPECTIO	N REPORT	JOB	NO. <u>10-8443 - 05</u>
•			DIST	TRICT 7B
	•		•	MUST WITNESS
OPERATOR UNIDENTIFIED	·····	LEASE/ID		Field Initiated
LEASE/FACILITY LIPSKY PROPERTY		DRILL PMT, NO.	<del></del>	Taken By
WELL No.(s) WATER WELL	<u></u>	PLANT NO.		District Austin
FIELD		PIT PMT. NO.		☑ Backcheck
COUNTY PARKER	COSTAL MGT AREA	PIPELINE PMT NO.	<u> </u>	Co-inspection
✓ COMPLAINT NO. 7B-9601	<del></del>	OTHER		Sweep
COMPLAINANT NAME STEVE LIPSKY		LE DOCKET		TOTAL:
DIRECTIONS	·	SFP CODE		UIC WELLS INSP
		SFCU CODE		WELLS INSP
				SITES INSP 1
		% TIME UIC	ENV	SITE REM
		LEGAL ENF	PRO/PROD	TERRA
		SFP	OTHER	
GPS COORDINATES: NO YES LOG#				
LAT LONG	FIEL	D INSPECTION STATU	S <u>COMPLIANCE</u>	Prev New Total
			yes no	viols, viols, viols,
ACTIVITY (check appropriate boxes)	SWR 2	Access to Propert		
A ☐ BLOWOUT P ☐ OIL SPILL	(NON SEN) SWR 3	Signs		
B COM. SURFACE DISP. FAC. Q OIL SPILL	(SENS) SWR 8	Water Protection		1 0 1
C COM DISPOSAL WELL R PIT INSPE	CTION SWR 9	Disposal Wells		
D FLARE/VENT S PLANT INS	P SWR 13	Casing/Cementing		
E DISPOSAL/INJECTION T PLUGGING	100 M	en elsen och else er er kan bensans bestär vitt er i Ra		<u> </u>
F DRILLING RIG U PLUGGING	The second of th	Control of the Market State of the State of the Control of the Con		
G ☐ FIRE V ☐ PROD WAT	Constitution of the contract o	To be with the first transfer of the second of the second of		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
H ☐ H2S COMPLIANCE INSP. W ☐ PROD TES	CORP A CONTRACT OF STREET OF	tion vitamani miskon liner viewani na si		
H H2S INCIDENT X PROD/INT		Manager Indicates to the Manager and the chief		
The property of the control of the c	Attaches Selvener	ett. De Seite ett att bet etter bestere		
	and the second s	and the second of the second o		
K☑ LEASE INSPECTION Z☐ SITE ASSM		.,,		
L MIT AA SITE CLEAN	The second section of the second section of the second section of the second section s			
MINOR PERMIT BE SURFACE C	The state of the s	Oil Spill Clean-up	on and <b>one</b> in the control in the c	
N OFFICE CC WASTE HAI	No. 2 70 1 19 April 27 12 14 14 15 15 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16			
OTHER .	OTHER			<u></u>
Comments: SWR 2: OK				
JOINT INSPECTION WITH DOUG ALLMA		**************************************		(WOLF EAGLE
ENVIROMENTAL), BRYN MEREDITH AN				
CATCH TWO GAS SAMPLES FROM WA	TER WELL CASI	NG TO SEND TO	LAB FOR ANAI	LYSIS.
STEVE LIPSKY STATED THEY ARE GOI	NG TO DISCONT	INUE USE OF T	HE WELL FOR H	IOUSE USE.
THE 5000 GALLON HOLDING TANK WIL	L BE WASHED (	OUT AND FILLE	WITH POTABL	E WATER.
CERTIFY THIS DATA IS TRUE AND COMPLETE:	MILEA	GE TIME	LUNCH	OFFICE REVIEW
Bulla Jonan	START: 173,		60 (MIN)	
TECH NO. 363 DATE 08/26/10	END: 174,0		Job Interrupt	DATE /9/21/10

RAILROAD COMMISSION OF TEXAS					D-O
Oil and Gas Division	District		IOD	Ar.	4
Compliance Section	INSPECTION	ON REPORT	DIST	NO. 10-8443 💛	/
			ופוס	MUST WITNESS	
OPERATOR UNIDENTIFIED		LEASE/ID	-	Field Initiated	
OPERATOR UNIDENTIFIED  LEASE/FACILITY LIPSKY PROP. WATER WI	F1 I	DRILL PMT. NO.		Taken By	
	up fau las	PLANT NO.		- <u></u>	stin ം
WELL No.(s) FIELD		PIT PMT, NO.		☑ Backcheck	-1.
	TAL MGT AREA	PIPELINE PMT NO.		✓ Co-inspection	i.
COMPLAINT NO. 7B-9601	IAL PIGT AKLA	OTHER		Sweep	£1
COMPLAINANT NAME STEVE LIPSKY	<del></del>	LE DOCKET		TOTAL:	
DIRECTIONS		SFP CODE		UIC WELLS INSP	
		SFCU CODE		WELLS INSP	
				SITES INSP	
		* *			
		% TIME UIC	ENV	SITE REM	
		LEGAL ENF	PRO/PROD	TERRA	
		SFP	OTHER		
GPS COORDINATES: NO YES LOG#					
LAT N32.56312 LONG W97.79144	FIE	LD INSPECTION STATUS	COMPLIANCE	Prev New T	otel
	amaronate no	orende karnanga karnangan dengan dengan dengan periodikan dengan dalah dengan dengan dengan dengan dengan deng Dengan dengan denga	yes no	viols, viols, vi	iols.
ACTIVITY (check appropriate boxes)	SWR	2 Access to Property			
A BLOWOUT PE DOIL SPILE (NON	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	and or the second secon		e en como an a pareza de Mercano en tampo de aporte de Seix e en esta en	alise news walkin
B ☐ COM. SURFACE DISP. FAC. Q ☐ OIL SPILL (SENS	OCCUPANT IN THE PROPERTY OF STATE OF ST	8 Water Projection			
G COMEDISPOSAL WELL) R PITEINSPECTION	SERVICE II			in so a rang managanah Managanah di managan da lan kanagan	ainamanin'i 2
D FLARE/VENT S PLANT INSP	SWR	PROPERTY THE RESIDENCE AND ADDRESS OF THE PROPERTY OF THE PROP			
E DISPOSAL/INJECTION IN PEUGGING (OPE	Particular de la constant de la cons	14(B)(2) Inactive wells			SE HARRING
F ☐ DRILLING RIG U ☐ PLUGGING (SFP		17 Pressure on Bradent	iesd		
G FIRE VI □ PROD WATER S	ACCESSAGE BONCONNE	ENDONE DE LA COMPANSION			is amest
H  H2S COMPLIANCE INSP. W PROD TEST	SWR	张尔克斯·加州·加州·加州·加州·西州·西州·西州·西州·西州·西州·西州·西州·西州·西州·西州·西州·西州			
HZS INCIDENT X PROD/INT CASI	CHICAGO AND DESCRIPTION OF STREET	GOOD CONTRACTOR CONTRA			an wa ka
J HYDROCARBON STRING Y SEAL WELL	SWR	HARLINGSANDERSTEIN STEIN STANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERSTANDERS			
KU LEASE INSPECTION Z' STIE ASSMI (SE	Secretarian em				100
L MIT AA SITE CLEAN UP	management   Parcing the same	DESTROY CONTRACTOR SENSE SENSE SENSE			
MINGRIPERMIT BB SURFACE CASIN	Contraction of the contraction o	calling the contract of the design of the contract of the cont			Notes 4
N OFFICE CC WASTE HAULER	SERVICE STATES OF THE SERVICE OF THE	Kingle 1. The state of the stat			色色岩
O CITHERIU	OTHE	<u> </u>	<del></del>		
Comments:  JOINT INSPECTION WITH STEVE AND SHY	I A LIDEVV	DAVID DITTED AL	ID DOVN MEDE	INTU	····
TAYLOR AND OLSON FIRM ATTNYS; ALISA					
JONAS, RRC	A RIGH, WO	EF EAGLE LITTING	MAINTER A LANCE OF T	JODDA JONAO.	<del> </del>
COLLECTED TWO TEDLAR BAG GAS SAM	DI ES EDO	THE CASING HEA	D OF THE LIP	SKY	
WATER WELL.	FLL3 FROM	H THE CASING HEA	ID OF THE EIR		
WAIER WELL.					
			·		
		NAME			<del></del>
				· · · · · · · · · · · · · · · · · · ·	
I CERTIFY THIS DATA IS TRUE AND COMPLETE:	AAH I	EAGE TIME	LUNCH	OFFICE BEVIEW	
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		),544 8:00	60 (MIN)		
TECH NO. 457 DATE 08/26/10 END		706 17:00	☐ Job Interrupt	DATE 9/2//	72
TOTAL DOTAL		,	ago monupe		

Well Report: Tracking #:108518

STATE OF TEXAS WELL REPORT for Tracking #108518

Owner:

Steve Lipiske

Owner Well #:

No Data

Address.

Silverado Addition

Grid #:

32-26-6

Well Location:

Silverado Addition

Latitude:

32" 33' 43" N

Weatherford, TX 76086

Weatherford, TX 76086

Longitude:

097° 46' 48" W

Well County:

Parker

Elevation:

No Data

**GPS Brand Used:** 

map

Type of Work:

**New Well** 

Proposed Use:

Domestic

**Drilling Date:** 

Started: 4/11/2005

Completed: 4/11/2005

Diameter of Hole:

Diameter: 7 in From Surface To 200 ft

**Drilling Method:** 

**Air Rotary** 

Borehole

Gravel Packed From: 60 ft to 200 ft

Completion:

Gravel Pack Size:

Annular Seal Data:

1st Interval: From 0 ft to 60 ft with 3 (#sacks and material)

2nd Interval: No Data 3rd Interval: No Data Method Used: Grout Cemented By, Larry Peck

Distance to Septic Field or other Concentrated Contamination: 150 ft

Distance to Property Line: No Data Method of Verification: Tape Approved by Variance: No Data

Surface Completion: Alternative Procedure Used

Water Level:

Static level: 65 ft, below land surface on 4/11/2005

Artesian flow: No Data

Packers:

No Data

Plugging Info

Casing or Cemant/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 180 ft

Well Tests:

Yield: 18 GPM with 90 ft drawdown after 3 hours

Water Quality

Type of Water: Good Depth of Strata: No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller

understood that failure to complete the required items will result in the log(s) being returned for

completion and resubmittal.

000255

Well Report: Tracking #:108518

Company information: Peck's Water Well Service, Inc. 2650 White Settlement Road Weatherford, TX 76087

**Driller License** 

1598

Number

Larry Peck

Licensed Well **Driller Signature:** 

Registered Driller **Apprentice** 

No Data

Signature:

**Apprentice** Registration Number:

No Data

Comments:

\$dfs

Surface Completion: Steel Sleeve

This well is located near the Parker/Hood County Line.

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #108518) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

## DESC. & COLOR OF FORMATION MATERIAL

From (it) To (ft) Description 0-3 Top Soil 3-18 Clay Gravel Sand Layers 18-35 Yellow Clay Sand 35-60 Green Shale with Rock 60-90 Shale with Sand 90-140 Green Shale Gravel Sand Layers 140-145 Red Bed 145-190 Green Shale with Sand Layers 190-200 Red Bed

CASING, BLANK PIPE & WELL SCREEN DATA

Setting From/To Dia. New/Used Type 4 New Plastic 0 180 4 New Plastic, Slotted 180 200 .020

000256

## ANACON, INC.

730 FM 1959 HOUSTON, TX 77034



ANALYTICAL AND CONSULTING LABORATORIES

PHONE: (281) 922-7000 + FAX (281) 481-0089

September 08, 2010

Doug Allmand Railroad Commission of Texas - Abilene 3444 N. First St., Suite 600 Abilene, TX 79603

TEL: (325) 677-3545 FAX (325) 677-7122

RE:

Dear Doug Allmand:

Order No.: 1008279

Anacon, Inc. received 2 samples on 8/27/2010 for the analyses presented in the following report.

Analyses are performed with method-required QA/QC samples. These data are provided along with the sample results. There were no problems with the analyses unless noted in a Case Narrative.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

James Lee, Lab Manager

008

Total Number of Pages \_\_\_\_\_(Including Data Package Cover Sheet)

THIS DOCUMENT MEETS NELAC STANDARDS NELAC CERTIFICATE # T104704206-010-1

Date: 08-Sep-10

CLIENT:

Railroad Commission of Texas - Abilene

Project:

Ramoad Commission of Londo Transmission

Lab Order:

1008279

**CASE NARRATIVE** 

Anacon, Inc. received one gas sample to be analyzed for refinery analysis. The sample was sent to SPL for analysis.

002

Page 1 of 1

## Sample Receipt Checklist

Client Name RRC-ABILENE				Date and Tin	ne Receive		8/27/2010
Work Order Numbe 1008279				Received by:	cc	.*	
Checklist completed by Signature	8/27/18	)	· ·	Reviewed by	Initials	M 8	Dale
Matrix Our	Carrier name:	FedEx	•				
Shipping container/cooler in good condition?		Yes 5	<b>Z</b>	No 🔲	Not Present		
Custody seals intact on shippping container/co	ooler?	Yes 5	<b>Z</b>	No 🗀	Not Present		
Custody seals intact on sample bottles?	· ·	Yes [		No 🗍	Not Present	<b>2</b>	
Chain of custody present?		Yes 5	Z	No 🗆			
Chain of custody signed when relinquished and	d received?	Yes 5	2	No 🗀			
Chain of custody agrees with sample labels?		Yes 5	2	No 🗀		•	
Samples in proper container/bottle?	,	Yes 🕏	Z	No 🗆			
Sample containers intact?		Yes V	2	No 🗀		•	:
Sufficient sample volume for indicated test?		Yes &	2 .	No 🗀		100	76. 200
\li samples received within holding time?		Yes 🗓	<b>3</b> 1	No 🗆		(40)	3 (-3)
Container/Temp Blank temperature in compliar	ice?	Yes 🗹	<b>2</b> 1	No 🗆		$\sim r$	3°C-3) ).3°C
Water - VOA vials have zero headspace?	No VOA vials submi	Ited 🗵	2	Yes 📮	No 🗃	حال	ルoo C
Water - pH acceptable upon receipt?		Yes 🗌	J	Vo <b>☑</b>			
	Adjusted?		Checke	ed by	,		
•							
Any No and/or NA (not applicable) response mo	ust be detailed in the cor	nments	section be				
			====				
Client contacted	Date contacted:			Person	contacted		1 1
Contacted by:	Regarding:				-	Test int This vertetilised in	
Comments:						-	
			*			· · · · · · · · · · · · · · · · · · ·	
Corrective Action	The second secon					-	
TO STORES AND COMMENT OF THE PERSON OF THE P	er i er unionamente esta catacham net per per mana.		**** * * * * * * * * * * * * * * * * * *	**************************************	The state of the state of	na in an	·
	en e		Province of Sphilliages are come on an	The state of the s			- The state of the

na3



PAGE 1 OF 3

2010080524-001A

HOUSTON LABORATORIES

USED INTERCHANGE DRICK HOUSTON, TEXAS 77:54 PRONG (713) 660-0001

Sample ID.: 1008279-01A Gas

: Tedlar Bag : 08/26/10 11:30

For

: Anacon

Attn.

: Melissa Knight

: 730 FM 1959

Houston Texas 77034

Comments: Analyst JH Date Analyzed 8/31/2010

TCD Analysis:

COMPONENTS	MOL %
Hydrogen	0.000
Carbon Dioxide	0.031
Ethylene	0.000
Ethane	5.151
Acetylene	0.000
Argon/Oxygen	4.109
Nitrogen	19.698
Methane	68.244
Carbon Monoxide	0.000

Specific Gravity

0.7172

(Air = 1.000 @ 60F)

Net

Gross

BTU/ft3

775.7 'Dry

858.4 Dry

(@14.65 & 60F)

762.2 Wet

843.5 Wet

SOUTHERN PETROLEUM LABORATORIES, INC.

as Staley

Hydrocarbon Laboratory Manager

 $00^{4}$ 



PAGE 2 OF 3

HOUSTON LABORATORIES

HOUSTON, TEXAS TOOM PRODUCTOR TEXAS TOOM PRODUCTOR SERVING

CERTIFICATE OF ANALYSIS NUMBER:

2010080524-001A

Sample ID.: 1008279-01A Gas

: Tedlar Bag

For

: Anacon

Attn.

: Melissa Knight

: 730 FM 1959

Houston Texas 77034

## FID Analysis:

* *		
COMPONENTS		MOL %
Hexanes Plus		0.121
Methane	-	68.244
Ethane/Ethylene		5.151 / 0.000
Propane		1.76 <b>7</b>
Propylene		0.000
iso-Butane		0.274
Propadiene		0.000
n-Butane		0.418
Butene-1		0.000
Neo-Pentane	•	None Detected
iso-Butene	•	0.000
trans-Butene-2		0.000
cis-Butene-2		0.000
1,3-Butadiene		0.000
iso-Pentane		0.105
n-Pentane		0.082

SOUTHERN PETROLEUM LABORATORIES, INC.

as Staley

Hydrocarbon Laboratory Manager

005



PAGE 3 OF 3

2010080524-001A

HOUSTON LABORATORIES

0920 INTERCHANGE DEIVE HOUSTON, FEXAS 7/054 PHONE (713) 660-0801

Sample ID.: 1008279-01A Gas

: Tedlar Bag

For

Anacon

Attn.

: Melissa Knight

: 730 FM 1959

Houston Texas 77034

## Completed Analysis:

Component	MOL %		WT%	
Hydrogen	0.000		0.000	
Carbon Dioxide	0.031		0.066	
Carbon Monoxide	0.000		0.000	
Ethylene	0.000		0,000	
Acetylene/Propylene	0.000 /	0.000	0.000	/ 0.000
Argon/Oxygen	4.109		6.329	•
Nitrogen	19.698		26.575	
Methane	68.244		52.696	
Ethane	5.151		7.455	
Propane	1.767		3.750	
iso-Butane	<b>0,274</b> .		0.767	
Propadiene	0.000		0.000	
n-Butane	0.418		1.169	
Butene-1	0.000		0.000	
Neo-Pentane	0.000		0.000	
iso-Butene	0.000		0.000	
trans-Butene-2	0.000		0.000	
cis-Butene-2	0.000		0.000	
1,3-Butadiene	0.000		0.000	
Iso-Pentane	0.105		0.365	
n-Pentane	0.082		0.285	
Hexane Plus	0.121	•	0.543	
	100.000		100.000	

SOUTHERN PETROLEUM LABORATORIES, INC.

as Stay

Hydrocarbon Laboratory Manager

008



Expires

Name

CC#

SPL, Inc. PO Box 842013 Dallas, Texas 75284-2013 (713) 660-0901 Phone (713) 660-8975 Fax

1030532939 Invoice No. **Customer No ANACON** 

Invoice

Office Use Only

iomei	) (	0.004.00040
	1 3	8/31/2010
	1 1	2010080524
		Melissa Knight
Houston Texas 77034	) (PO#	1008279-CC
		TOTAL
		TOTAL
Refinery Gases-TCD/FID-ASTM D-1946/1945M	\$275.00	\$275.00
	1.0	·
·		
	· SubTotal	\$275.00
yment Details Shi	ipping & Handling	\$0.00
		\$0.00
Check		
Credit	TOTAL	\$275.00
	Anacon, Inc Accounts Payable/Melissa Knight 730 FM 1959 Houston Texas 77034   Description Refinery Gases-TCD/FID-ASTM D-1946/1945M   yment Details Cash Check  Sh Taxe	Anacon, Inc Accounts Payable/Melissa Knight 730 FM 1959 Houston Texas 77034  Description Refinery Gases-TCD/FID-ASTM D-1946/1945M  SubTotal yment Details Cash Check  Date Order No. Rep PO#  Unit Price  SubTotal Shipping & Handling Taxes State

Southern Petroleum payment terms are net 30.

Page 1 **NET 30** 

Thank You for Your Business

ANACON, INC. 730 FM 1959 HOUSTON, TX 77034-5422

(281) 922-7000 Voice: (281 922-9158 Fax:

Invoice Number: 119314-1008279 Invoice Date:

Sep 13, 2010

Page:

Net 30 Days

Abilene District RR Comm. District Director 3444 N. First St., Suite 600 Abilene, TX 79603	Abilene District RR Comm. District Director 3444 N. First St., Suite 600 Abilene, TX 79603
	Appropriate space management according formatter and advanced as a specific field the property design and a second according to the second according t

TXRR-ABILENE		Net 30 D	
Sales Rep(D.	Shipping Method	Ship Date	Due Date 10/13/10
Quantity Item 1.00   MISC	Description REFINING GASES	Unit Price( ) 275.00	Amount 275.00
			d.
	Ť		
	Subtotal		275.0
	Sales Tax Total Invoice Amount		275.0
Check/Credit Memo No:	Payment/Credit Applied FOTAL		275

: Luy

Dame of many

QAP. Revision 2.7

Anacon Log Number: 1008270 Romarks Page / of THE COLUMN TO TH 풀 Type of Analysis Requested Turn Around Time: Time: إغ Due Date: Dalo: Dale: Oalo: Chain of Custody Record Contact Porson: Lary Almand Phone Number: (325)(77-3545 (325) 677-7122 Sicher Alto 292 Xメ Date: 956/o Time: 17:00 Remoushed Br. Retroutshed By: Accepted By: Accepted By Delivered By: FRORY #8 LOST. SIGHT-445 Sampled By: Fax Number: Client Sample ID 4 Caling # 1 Time C. 3 Casting 11me: Jano: 76-9/601 Numbor of Containers 20.30 Officis: Stad 92410 11:30 1 tedber 14.6 Date; Osta: Car S. 2020 E. Client: Railson Comission 1 x 1/2 16.7em Dist 78 Data/Time Collected 8/24/0 11:3. Minand CXAS ANACON, INC. 720 FM 1859 HOLSTON, TX 77034 [281] 822-7000 TM [261] 481-6089 FM Custody Seal (Y/N): Well-Ca Sample Matrix St. Gas Temperature: Complet By. Log Number Reinquished By. Reinquished By Leke Accepted By.



PAGE 1 OF 3

2010090089-001A

**HOUSTON LAB** 8820 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 PHONE (713) 660-0901

Bradenhead gas Semple

Sample ID.: Butler 1-H

Surfaçe Casing

: 22 psig @ 70° F

: Received 9/8/2010

For

: Texas Fabco Inc.

Attn.

: John Baker

: P.O. Box 1174

Granbury Texas 76048

Comments: Analyst JH Date Analyzed 9/8/2010

TCD Analysis:

COMPONENTS	MOL %
Hydrogen/ Helium	0.304
Carbon Dioxide	0.032
Ethylene	0.000
Ethane	0.538
Acetylene	0.000
Argon/Oxygen	0.039
Nitrogen	7.389
Methane	91.481
Carbon Monoxide	0.000

Specific Gravity (Air = 1.000 @ 60F) 0.5888

Net 844.4 Dry Gross

BTU / ft3 (@ 14.65 & 60F)

829.7 Wet

937.9 Dry 921.6 Wet

SOUTHERN PETROLEUM LABORATORIES, INC.

Hydrocarbon Laboratory Manager



PAGE 2 OF 3

HOUSTON LAB 8820 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 PHONE (713) 860-0901

CERTIFICATE OF ANALYSIS NUMBER:

2010090089-001A

Sample ID.: Butler 1-H

Surface Casing

: 22 psig @ 70° F

For

: Texas Fabco Inc.

Attn.

: John Baker

: P.O. Box 1174

Granbury Texas 76048

FID Analysis:

COMPONENTS		MOL %
Hexanes Plus		0.012
Methane		91.481
Ethane/Ethylene	•	0.538 / 0.000
Propane		0.140
Propylene	•	0.000
iso-Butane		0.019
Propadiene		0.000
n-Butane		0.033
Butene-1		0.000
Neo-Pentane		None Detected
iso-Butene		0.000
trans-Butene-2		0.000
cis-Butene-2		0.000
1,3-Butadiene		0.000
iso-Pentane		0.007
n-Pentane		0.006

SOUTHERN PETROLEUM LABORATORIES, INC.

Cas Staley

Hydrocarbon Laboratory Manager



PAGE 3 OF 3

2010090089-001A

HOUSTON LAB 8920 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 PHONE (713) 060-0901

Sample ID.: Butler 1-H Surface Casing

: 22 psig @ 70° F

For

: Texas Fabco Inc.

Attn.

: John Baker

: P.O. Box 1174

Granbury Texas 76048

Completed Analysis:

Component	MOL %		WT%	
Hydrogen/ helium Carbon Dioxide	0.304 0.032		0.036 0.083	
Carbon Monoxide	0.000		0.000	
Ethylene	0.000		0.000	
Acetylene/Propylene	0.000 /	0.000	0.000 /	0.000
Argon/Oxygen	0.039		0.073	
Nitrogen	7.389	*	12.144	
Methane	91.481		86.055	
Ethane	0.538		0.949	•
Propane	0.140		0.362	
iso-Butane	0.019		0.065	
Propadiene	0.000		0.000	
n-Butane	0.033	• •	0.112	4
Butene-1	0.000		0.000	
Neo-Pentane	0.000		0.000	
iso-Butene	0.000		0.000	-
trans-Butene-2	0.000		0.000	
cis-Butene-2	0.000		0.000	
1,3-Butadiene	0.000		0.000	
iso-Pentane	0.007		0.030	
n-Pentane	0.006		0.025	4.
Hexane Plus	0.012		0.066	٠
	100.000		100.000	*

SOUTHERN PETROLEUM LABORATORIES, INC.

as Stay

Hydrocarbon Laboratory Manager

# SPL, Inc. Analysis Request Chain of Custody Record

Note - As a convenience to our clients, this form is available in an electronic format. Please contact one of our offices above for the form to be e-mailed to you.

#### J-W MEASUREMENT COMPANY

Shreveport, LA Tyler, TX Fairfield, TX Victoria, TX Godley, TX Broussard, LA Zapata, TX WWW.JWOPERATING.COM 888-226-9110

**Date Sampled** : 02/16/2010 : 19505701307 J-WMC Number **Date Analyzed** : 02/16/2010 : TEXAS FABCO INC. Customer **Effective Date** : 03/01/2010 : 1307 Station ID Pressure : 142.0 Station Name : BUTLER # 1-H Temperature (F) : RANGE RESOURCES : 89.0 Area Cylinder ID : 1732 : HOOD County/Parish Sampled by ; JM State : TX **Property Cd** 

COMPONENT		MOL %	GPM @ 14.696(PSIA)
Methane		77.2336	0.000
Ethane		12.5110	3.337
Propane	. <del>-</del>	4.4428	1.221
Iso-Butane		0.6131	0.200
Normal-Butane		1.2582	0.396
Iso-Pentane		0.3698	0.135
Normal-Pentane		0.4328	0.156
Hexanes++		1.4451	0.625
Nitrogen		1.2433	0.000
Carbon-Dioxide	2	0.4503	0.000
TOTAL		100,0000	6.071

Compressibility Factor (Z) @ 14.696 PSIA @ 60 DEG. F =

0.751

0.9961

Ideal Gravity: 0.748

· tour of writing							
BTU @ (PSIA)		@14.65	@14.696	@14.73	@15.025		
GPM	*.	6.052	6.071	6.085	6.207		
Ideal BTU Dry		1276.50	1280.50	1283.47	1309.17		
Ideal BTU Sat		1254.16	1258.17	1261.13	1286.83		
Real BTU Dry		1281.43	1285.47	1288.45	1314.36		
Real BTU Sat		1259.42	1263.47	1266.45	1292.36		

#### Comments:

12/2016

Real Gravity:

**METHOD: GPA 2261-00** 

Note: Calibration, Standards, and testing procedures are archieved pursuant to GPA regulations.

This Analysis Report is not intended for submission to Lousiana Department of Environmental Quality.

Deborah Murphy

G



#### **DFW LABORATORIES**

2440 Chambers Street, Suite A Venus, TX 76084 PHONE (817) 539-2168 FAX (817) 539-2170

## **Certificate of Analysis**

Number: 3040-2010090011-001A

September 02, 2010

Sean Baker P.O. Box 1174 Grandbury TX 76084 United States Of America

Sample ID:

Station Name:

**Butler 1H** 

Station Number:

**B001INJ** Barnett Shale

Station Location: Sample Point:

Surface Casing

Sampled By:

S. Baker

Sample Of:

Natural Gas Spot

@ 70.0°F

Sample Date: Sample Conditions: 09/02/2010

22.0 psig,

PO / Ref. No: Effective Date:

**ANALYTICAL DATA** 

Components	Mol %	Wt %	GPM at 14.650 psia	Method	Lab Tech.	Date Analyzed
				GPA-2261 M	LM	9/2/2010
Nitrogen	7.200	11.794				
Carbon Dloxide	0.013	0.033				
Methane	91.979	86.280	* *			
Ethane	0.540	0.949	0.144			
Propane	0.137	0.353	0.038			
Iso Butane	0.019	0.065	0.006	the second second		
n-Butane	0.033	0.112	0.010			
Iso Pentane	0.007	0.030	0.003			
n-Pentane	0.007	0.030	0.003	ranten and and the same of the same supplementaries and same supplementaries.	an hitter i lah mit itw -amiabibibibit-	
Hexanes Plus	0.065	0.354	0.028	•		
	100.000	100.000	0.232			
	C2 +	C3 +	IC5 +			
GPM TOTAL:	0.232	0.088	0.034			
Relative Density	Real Gas			0.5914		
Calculated Molecular \	<b>Neight</b>			17.10		•
Compressibility Factor	_			0.9981		
Calculated Gross BTU	per ft³ @14.650 ps	ia & 60°F				
Real Gas Dry	Basis	946				

Saturated Basis

930

Comments:

Cylinder Number

Bould I . C. en fre.

Hydrocarbon Laboratory Manager

**Quality Assurance:** 

The above analyses are performed in accordance with ASTM, UOP or GPA guidelines for quality assurance, unless otherwise stated

Page 1 of 1

## ANACON, INC.

730 FM 1959 HOUSTON, TX 77034



ANALYTICAL AND CONSULTING LABORATORIES

PHONE: (281) 922-7000 + FAX (281) 481-9089

August 30, 2010

Doug Allmand
Railroad Commission of Texas - Abilene
3444 N. First St., Suite 600
Abilene, TX 79603

TEL: (325) 677-3545 FAX (325) 677-7122

RE:

Dear Doug Allmand:

Order No.: 1008199

Anacon, Inc. received 4 samples on 8/18/2010 for the analyses presented in the following report.

Analyses are performed with method-required QA/QC samples. These data are provided along with the sample results. There were no problems with the analyses unless noted in a Case Narrative.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

James Lee, Lab Manager

Total Number of Pages (Including Data Package Cover Sheet)

THIS DOCUMENT MEETS NELAC STANDARDS NELAC CERTIFICATE # T104704206-010-1

Date: 30-Aug-10

CLIENT:

Railroad Commission of Texas - Abilene

Project:

Lab Order:

1008199

**CASE NARRATIVE** 

Anacon, Inc. received one water sample to be analyzed for anions, cations, alkalinity, TDS, TPH, BTEX, and pH. The sample was received in good condition and within hold times required for analysis. There was a QC problems noted with the MSD for sodium, however, the sample spiked was from a different client. Also, one of the TPH surrogates in the sample was below the acceptance limits. All QC has been included for review.

02

An	ac	ดท	ı	nc
7311	au	•		

## Sample Receipt Checklist

Client Name RRC-ABILENE		Date and Time Receive	8/18/2010
Work Order Numbe 1008199		Received by: CC	:
Checklist completed by Signature	8/18/10	Reviewed by Initials	( 8   8   0
Matrix: Water ca	rrier name: <u>FedEx</u>		
Shipping container/cooler in good condition?	Yes 🗹	No Not Present	]
Custody seals intact on shippping container/cooler?	Yes 🗹	No [ ] Not Present [	] .
Custody seals intact on sample bottles?	Yes 🗆	No 🗌 Not Present 🖟	<b>Z</b>
Chain of custody present?	Yes 🗹	No 🗀	
Chain of custody signed when relinquished and received?	Yes 🔽	No 🗆	
Chain of custody agrees with sample labels?	Yes 🗹	No 🗆	• .
Samples in proper container/bottle?	Yes 🗹	No 🗆	
Sample containers intact?	Yes 🗹	No 🗆 💮	e.1°C-3)
Sufficient sample volume for indicated test?	Yes 🗹	No 🗆	
All samples received within holding time?	Yes 🗹	No 🗀	
Container/Temp Blank temperature in compliance?	Yes 🗹	No 🗀	3.1°C
Water - VOA vials have zero headspace? No VOA	A vials submitted	Yes 🗹 No 🗌	•
Water - pH acceptable upon receipt?  Adjusted?	Yes ☑ NO	No □ Checked by CC	•
Any No and/or NA (not applicable) response must be detained and the second and th	iled in the comments se	ction be	
Client contacted Date cont	acted:	Person contacted	
Contacted by: Regarding	):		
Comments:			*.
			e de la companya del companya de la companya del companya de la co
			moterna managa a mata a mata a mata da
Corrective Action			
		ere, per egge <u>andere a menter andere de l'antière de l'antière de l'antière de l'antière de l'antière de l'antière de</u>	oronna armadan urbumban ( k. 1994). Makatan sa uraban ( k. 1904). Makatan kalaban ( k. 1994). Makatan ( k.
	,	and the state of t	management of the state of the
end de la companya de la principa de la companya de la forma de Pendende Philosophica de dels de la companya de disposance de la companya del companya de la companya del companya de la companya del la companya del la companya del la companya de la companya de la companya de la companya del	and the state of t		03

Date: 27-Aug-10

CLIENT:

Railroad Commission of Texas - Abilene

Client Sample ID: 6

Lab Order:

1008199

Collection Date: 8/17/2010 10:00:00 AM

Project:

Lab ID:

1008199-001

Matrix: WATER

Analyses	Result	Limit Q	ual Units	DF	Date Analyzed
ICP METALS		E200.7	Analyst: HN		
Calcium	1.32	0.0420	mg/L	. 1	8/27/2010 11:56:00 AM
Magnesium	0.531	0.134	mg/L	1	8/27/2010 11:56:00 AM
Potassium	1.04	0.166	mg/L	1	8/27/2010 11:56:00 AM
Sodium	250	0.0510	mg/L	. 1	8/27/2010 11:56:00 AM

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

\* - Value exceeds Maximum Contaminant Level

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

04

E - Value above quantitation range

Page 1 of 4

Date: 27-Aug-10

CLIENT:

Railroad Commission of Texas - Abilene

Client Sample ID: 5

Lab Order:

1008199

Collection Date: 8/17/2010 10:00:00 AM

Project:

Lab ID:

1008199-002

Matrix: WATER

Analyses	Result	Limit Q	ial Units	DF	Date Analyzed	
ANIONS BY ION CHROMATOGRAPHY	E300				Analyst: KK	
Chloride	24.0	0.500	mg/L	1	8/20/2010	
Suifate	0.750	0.500	mg/L	1	8/20/2010	
ALKALINITY	M2320 B			-	Analyst: JS	
Bicarbonate	577	2.00	mg/L	1 .	8/19/2010	
Carbonate	ND	2.00	mg/L	. 1	8/19/2010	
ЭН	E150.1				Analyst: JS	
pH	8.83	0	pH units	1	8/19/2010	
TOTAL DISSOLVED SOLIDS		M2540	C		Analyst; JS	
TDS	646	2.00	mg/L	. 1	8/24/2010	

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

\* - Value exceeds Maximum Contaminant Level

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

05

E - Value above quantitation range

Page 2 of 4

Date: 27-Aug-10

CLIENT:

Railroad Commission of Texas - Abilene

Client Sample ID: 3,4

Lab Order:

1008199

Collection Date: 8/17/2010 10:00:00 AM

Project:

Lab ID:

1008199-003

Matrix: WATER

Analyses	Result	Limit Qual	Units	DF	Date Analyzed
TPH FOR WATER		Analyst: JL			
TPH (C6 - C35)	ND	5.00	mg/L	· 1	8/19/2010
TPH (C6 - C12)	· ND	5.00	mg/L	1	8/19/2010
TPH (C12 - C35)	ND	5.00	mg/L	1	8/19/2010
Surr: 1-Chlorooctadecane	32.0	50-150 S	%REC	1	8/19/2010
Surr: 1-Chlorooctane	82.0	50-150	%REC	1	8/19/2010

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

\* - Value exceeds Maximum Contaminant Level

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

08

E - Value above quantitation range

Page 3 of 4

#### Anacon, Inc.

Date: 27-Aug-10

CLIENT:

Railroad Commission of Texas - Abilene

Client Sample ID: 1,2

Lab Order:

1008199

Collection Date: 8/17/2010 10:00:00 AM

Project:

Lab ID:

1008199-004

Matrix: WATER

Analyses	Result	Limit Q	ual Units	DF	Date Analyzed
VOLATILE ORGANIC COMPOUNDS	IN WATER BY	SW8260	В		Analyst: <b>KK</b>
Benzene	6.84	2.00	μg/L	. 1	8/18/2010 11:59:00 PM
Ethylbenzene	ND	2.00	μg/L	1 .	8/18/2010 11:59:00 PM
m,p-Xylene	ND	4.00	μ <b>g/</b> L	1	8/18/2010 11:59:00 PM
o-Xylene	ND	2.00	μ <b>g/L</b>	1	8/18/2010 11:59:00 PM
Toluene	6.12	2.00	μg/L	1	8/18/2010 11:59:00 PM
Surr: 1,2-Dichloroethane-d4	76.2	60-135	%REC	1	8/18/2010 11:59:00 PM
Surr: 4-Bromofluorobenzene	105	69-130	%REC	1	8/18/2010 11:59:00 PM
Surr: Dibromofluoromethane	97.9	62-130	%REC	1	8/18/2010 11:59:00 PM
Surr: Toluene-d8	130	62-135	%REC	1	8/18/2010 11:59:00 PM

Qualifiers:

ND - Not Detected at the Reporting Limit

J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method Blank

\* - Value exceeds Maximum Contaminant Level

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

17

E - Value above quantitation range

Page 4 of 4

Client ID:

77777

Sample ID: 1008227-014A-MS

SampType: MS

TestCode: 200.7

Units: mg/L

Prep Date:

Run ID: METAL-ICP-1\_100827A

00

SeqNo: 332452

%RPD RPDLimit Qual

Analysis 8/27/2010

TestNo: E200.7

Batch ID: R27035

Result

ညီ

SPK value

SPK Ref Val

%REC

LowLimit HighLimit RPD Ref Val

Sodium

Potassium Magnesium Calcium

0.1268 0.1151 0.9486 0.1294

0.0420 0.134 0.166 0.0510

0000

127 115 94.9 129

2222

3333

Result

SPK value

SPK Ref Val

%REC

LowLimit HighLimit RPD Ref Val

SeqNo: 332442

%RPD RPDLimit

Quai

Analyte

Calcium

Sodium Potassium Magnesium

Sample ID: 1008227-014A-MSD

SampType: MSD

TestCode: 200.7

Units: mg/L

Prep Date:

Run ID: METAL-ICP-1\_100827A

SeqNo: 332453

%RPD RPDLimit

Analysis 8/27/2010

TestNo: E200.7

652.3 359.8 137

0.0420 0.134 0.166 0.0510

5555 5555

552 264.1 27.96 4116

100 95.7 109 70.9

2222

130

0000

4187

Batch ID: R27035

Result

ğ

SPK value

SPK Ref Val

%REC

LowLimit HighLimit RPD Ref Val

655.6 358.3

0.0420

**3** 8

552 264.1

104 94.2

22

130 130

652.3 359.8

0.504

8 8

B - Analyte detected in the associated Method

Page 1 of 5

Client ID: ZZZZZ

Analyte

Qualifiers:

ND - Not Detected at the Reporting Limit J - Analyte detected helow quantitation limits

R - RPD outside accepted recovery limits S - Spike Recovery outside accepted recovery limits Magnesium Catcium Analyte

· ``
-
_
50
0
0
7–4
_
•
_
္ဂ

CLIENT: Work Order: 1008199 Railroad Commission of Texas - Abilene

Run ID: METAL-ICP-1_100827 SegNo: 332442	Prep Date: Analysis 8/27/2010	Pre	Units: mg/L	stCode: 200.7 TestNo: E200.7	TestCode: TestNo:	SampType: LCS Batch ID: R27035	Sample ID: LCS082510JS Client ID: ZZZZZ
					0.0420 0.134 0.166 0.0510	8888	Calcium Magnesium Potassium Sodium
%RPD RPDLimit Qual	mit HighLimit RPD Ref Val	%REC LowLimit	SPK Ref Val	SPK value	ညှ	Result	Analyte
Run ID: METAL-ICP-1_100827. SeqNo: 332441	Prep Date: Analysis 8/27/2010	Pre *	Units: mg/L	TestNo: E200.7	TestC Tes	SampType: MBLK Batch ID: R27035	Sample ID: BLK082510JS Client ID: ZZZZZ
00.7	TestCode: 200.7						Project:

Date: 30-Aug-10

08

ANALYTICAL QC SUMMARY REPORT

J - Analyte detected below quantitation limits

R - RPD outside accepted recovery limits

ANALYTICAL QC SUMMARY REPORT

CLIENT:
Work Order:

Railroad Commission of Texas - Abilene 1008199

Project:

Sample ID: 1008227-014A-MSD

SampType: MSD Batch ID: R27035

TestNo: E200.7

Units: mg/L

Result 136.8 4154

SPK value

SPK Ref Val

LowLimit HighLimit RPD Ref Val

Prep Date: Analysis 8/27/2010

Run ID: METAL-ICP-1\_100827A

0.166 0.0510

1 2 8

27.96 4116

109 37.4

70

130

137 4187

0.0911

25 25

%RPD RPDLimit

Analyte Client ID:

TestCode: 200.7

กร

Sample ID: Blank Client ID: ZZZZZ	Project:	CLIENT: Railroad C Work Order: 1008199
SampType: MBLK Batch ID: R26974	. *	Railroad Commission of Texas - Abilene 1008199
TestCode: 300_w2 TestNo: E300		lene
Units: mg/L		
Prep Date: Analysis 8/20/2010	TestCode: 300_w2	ANALYTICAL QC SUMMAR
Run ID: R	300_w2	UMMAR

Analyte

1	ALYTICAL QO
	<b>QC SUMMARY</b>
	 REPORT

		٠.								•
	Sulfate	Chlorida	Sample ID: 1008199-002amsd Client ID: 5	Sulfate	Analyte	Sample ID: 1008199-002ams  Client ID: 5	Chloride Sulfate	Analyte	Sample ID: LCS Client ID: ZZZZZ	Analyte Chloride Sulfate
	45.58 20.88	Result	SampType: msd Batch ID: R26974	45.63 20.7	Result	SampType: ms Batch ID: R25974	18.46 19.9	Result	SampType: LCS Batch ID: R26974	Result ND ND
	0.500		TestCade TestNa	0.500 0.500	PQL	TestCode TestNo	0.500 0.500	PQL	TestCode TestNo	PQL 0.500 0.500
	 20	SPK value	TestNo: E300_w2	, 20	SPK value	TestCode: 300_w2 TestNo: E300	20 20	SPK value	TestCode: 300_w2 TestNo: E300	SPK value
*.	24.03 0.7496	SPK Ref Val	Units: mg/L	24.03 0.7496	SPK Ref Val	Units: mg/L	00	SPK Ref Val	Units: mg/L	SPK Ref Val
	108 101	%REC		108 99.8	%REC		92.3 99.5	%REC		%REC
	90 110 45.63 90 110 20.7	LowLimit HighLimit RPD Ref Val	Prep Date: Analysis 8/20/2010	90 110 90 110	LowLimit HighLimit RPD Ref Val	Prep Date: Analysis 8/20/2010	90 110 90 110	LowLimit HighLimit RPD Ref Val	Prep Date: Analysis 8/20/2010	%REC LowLimit HighLimit RPD Ref Val
		'al %RPD RPDLimit Qual	Run ID: IC #1_100820A SeqNo: 331735	00		Run ID: IC #1_100820A SeqNo: 331734		'al %RPD RPDI imit Oual	Run ID: IC #1_100820A SeqNo: 331737	'al %RPD RPDLimit Qual
	•	Qual			Qual			2		Qual

S - Spike Recovery outside accepted recovery limits

R - RPD outside accepted recovery limits

Qualifiers:

ND - Not Detected at the Reporting Limit J - Analyte detected below quantitation limits

B - Analyte detected in the associated Method

Page 3 of 5

Qualifiers: ND - Not Detected  I - Analyte detected	Benzene Ethylbenzene m.p-Xylene	Analyte	ID: 1008187-001A ):	Surr. 1,2-Dichloroethane-d4 Surr. 4-Bromofluorobenzene Surr. Dibromofluoromethane Surr. Toluene-d8	tienzene Ethylbenzene m.p-Xylene o-Xylene Toluene	2	i.2:Dichloroethane-d4 t-Bromofluorobenzene Dibromofluoromethane Toluene-d8	Benzene Ethybenzene m.pXylene o-Xylene	ID: blank ):	Work Order: 1008199 Project:
ND - Not Detected at the Reporting Limit  J - Analyte detected below quantitation limits	51.23 59.13 119.9	Result	SampType: MS Batch ID: R26946	10.29 9.69 8.22 9.47	49.83 52.72 110.4 57.24 52.43	Batch ID: R26946 Result	11.07 9.91 11.5 10.43	Result	SampType: MBLK Batch ID: R26946	1008199
>α సు	2.00 2.00 4.00	PQL SPK value	TestCode: 8260_W TestNo: SW8260B		22422 8688 8688	TestNo: SW8260B	3.44 3.44 3.96	PQL SPK value 2.00 2.00 4.00 2.00	TestCode: 8260_W TestNo: SW8260B	
S - Spike Recovery outside accepted recovery limits R - RPD outside accepted recovery limits	50 50 0	ilue SPK Ref Val	W Units: µg/L 2608	00000	3888 3000	W Units: pg/L 260B	0 0 0	alue SPK Ref Vai	_W Units: pg/L 2608	
ocepted recovery	102 118 120	%REC L		103 96.9 82.2 94.7	99.7 105 114	%REC L	111 99.1 115 104	%REC L		<b>1</b>
· .	45 150 50 150 50 150	LowLimit HighLimit	Prep Date: Analysis 8/18/2010	2 2 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		Prep Date: Analysis 8/18/2010 LowLimit HighLimit F	60 135 69 130 62 130 62 136	LowLimit HighLimit	1 es Prep Date: Analysis 8/18/2010	ANALY HUA
3 - Analyte detected	000	RPD Ref Val	6	0000	0000	RPD Ref Val	0000	HighLimit RPD Ref Val	Run ID	T QCSUM
B - Analyte detected in the associated Method  Page 4 of 5		%RPD RPDLimit Qual	Run ID: MS-VOA-1_100818A SeqNo: 331411	0000	:	Run 1D: MS-VOA-1_100818A SeqNo: 331408  %RPD RPDLimit Qual	0000	%RPD RPDLimit Qual	OU_W Run ID: MS-VOA-1_100818A SeqNo: 331409	TICAL QC SUMMARY REPORT

11 000282 Pl. Appx. 000037

	·										-	
Qualifiers: ND - Not Detection  J - Analyte detection				Surr: Dibromofluoromethane Surr: Toluene-d8	Surr: 1,2-Dichloroethane-d4 Surr: 4-Bromofluorobenzene	o-Xylene Toluene	Ethylbenzene m,p-Xylene	Analyte	Sample ID: 1008187-001A Client ID: ZZZZZ	o-Xylene Toluene Surr. 1,2-Dichloroethane-d4 Surr. 4-Bromofluorobenzene Surr. Dibromofluoromethane Surr. Toluene-d8	Client ID: ZZZZZ  Analyte	ب
ND - Not Detected at the Reporting Limit J - Analyte detected below quantitation limits				7.62 10.52	11.07 9.61	66.49 63.7	50.79 62.41 131.6	Result	SampType: MSD Batch ID: R26946	61.91 58.39 8.84 9.3 8.49 10.06	Batch ID: R26946 Result	SampType: MS
				3.41 3.90	7.40 7.40	200	2.00 4.00		TestNo: SW8260B	2.00 2.00 6.33 7.40 3.41 3.90	TestNo: SWB260B	TestCode: 8260_W
S - Spik		. <u></u>		5 <b>5</b> .8	ಕಕ	 3 8 8	ទីនន	SPK value	260_W W8260B	1 1 0 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	SPK value	260_W
S - Spike Recovery outside accepted recovery limits R - RPD outside accepted recovery limits				000	<b>.</b>	1.72	<b>, ,</b> ,	SPK Ref Val	Units: µg/L	1.72 0 0 0	SPK Ref Val	Units: µg/L
cepted reco				76.2 105	B 11.	130	114 125	%REC		120 117 88.4 93 84.9 101	%REC	
very limits				62 62 64 62 62 64	383	5 5	5 5 5	LowLimit	Prep Date: Analysis	6,6,6,6,6,5,6,6,6,6,6,6,6,6,6,6,6,6,6,6	Analysit I	Preo Date:
. <b>B</b>			,	130	135	150	150	HighLimit	ep Date: Analysis 8/18/2010		8/18/201 fighLimit	
B - Analyte detected in the associated Method			~ .		58.39 0	119.9 61.91	51.23 59.13	RPD Ref Val		000000	RPD Ref Val	TestCode: 8260_W
od in the associa		·		000	8.70 0	9.31 7.13	10.3 5.40	%RPD	Run ID: MS-VO. SegNo: 331412	00000	SeqNo: 331411 SeqNo: 38PD RE	260_W
ted Method				222	20 20	22 22	22 23	RPDLimit	Run ID: MS-VOA-1_100818A SeqNo: 331412		SeqNo: 331411  %RPD RPDLimit Out	
יי ה								Qual	318A		Oval	

12

ANALYTICAL QC SUMMARY REPORT

CLIENT:
Work Order:
Project:

Railroad Commission of Texas - Abilene 1008199

#### QA/QC REPORT - LCS

Sample ID:

LCS

Matrix:

Aqueous Liquid

Anacon Number:

1008120, 121, 122, 160, 161, 199

Units

mg/L

Analyte / Method Number	Blk. Value	Spike Conc.	LCS Conc.	% Recovery	Recovery Limits
Alkalinity - 2320B	<2:00	100.0	97.9	98	80-120

LCS Advisory Limits

RPD:

0 out of 1 outside of QC limits

<sup>\*</sup>Matrix interference

<sup>\*\*</sup>Sample too concentrated to spike

#### QA/QC REPORT - MS/MSD

Sample ID:

MS/MSD

Anacon Number:

1008120, 121, 122, 160, 161, 199

Matrix:

Aqueous Liquid

Units

mg/L

Analyte/Method Number	Blank	Sample	Spike	MS	% REC	MSD	% REC	RPD	QC	LIMITS
			Level						RPD	% REC
Alkalinity - 2320B	< 2.00	2	100.0	98	96	98	96	0.00	10	80-120

## MS/MSD Advisory Limits

RPD:

0 out of 1 outside of QC limits

REC:

0 out of 2 oustide of QC limits

QA/QC Manager Million

REWISHN.

14

000285

Pl. Appx. 000040

<sup>\*</sup> Matrix Interference

<sup>\*\*</sup> Sample too concentrated to spike

#### QA/QC REPORT - LCS

Sample ID: Anacon Number: LCS

8211, 92, 93, 99

Matrix: Units Aqueous Liquid

mg/L

Analyte / Method Number	Blk Value	Spike Conc.	LCS Conc.	% Recovery	Recovery Limits
TPH-GRO - 1005	<5.0	50	55	110	75-125
TPH-DRO - 1005	<5.0	50	57	114	75-125

**LCS Advisory Limits** 

RPD:

0 out of 2 outside of QC limits

QA/QC Manager / Must

<sup>\*</sup>Matrix interference

<sup>\*\*</sup>Sample too concentrated to spike

#### QA/QC REPORT - MS/MSD

Sample ID:

MS/MSD

**Anacon Number:** 

8211, 92, 93, 99

Matrix:

Aqueous Liquid

Units

mg/L

Analyte/Method Number	DL	Sample	Spike	MS	% REC	MSD	% REC	RPD	QC	LIMITS
	<del> </del>		Level	····				·	RPD	% REC
TPH-GRO - 1005	<5	< 5	50	55	110	. 57	114	3.6	20	75-125
TPH-DRO - 1005	< 5	< 5	50	58	116	62	124	6.7	20	75-125

<sup>\*</sup>Matrix Interference

MS/MSD Advisory Limits

RPD:

out of 2 outside of QC limits

REC:

0 out of 4 oustide of QC limits

QA/QC Manager Mile Co


<sup>\*\*</sup>Sample too Concentrated for spiked amount

<sup>\*</sup> Matrix Interference

<sup>\*\*</sup> Sample too concentrated to spike

#### STAR DIAGRAM FROM WATER QUALITY ANALYSIS OF EACH SAMPLE INDICATED


Distances along each axis shows concentration of each (in milliequivalents per liter) expressed as a % of the total concentration of disolved solids.



1/2


Na + K Ca + Mg


PH: TDS:




Hell No. Lipsky Water Well

Well No.







Well No.

000288 Pl. Appx. 000043

SCALE: 07 Lipsky, Steve Complaint No. 7B-9601 Lipsky Property Water Well Parker County, Texas Job No. 10-8443

```
Sodium (Na) in Mg/L ? 250
Potassium (K) in Mg/L ? 1.04
Calcium (Ca) in Mg/L ? 1.32
Magnesium (Mg) in Mg/L ? .531
Chloride (Cl) in Mg/l ? .24
Sulfate (SO4) in Mg/l ? .7
Bicarbonate (HCO3) in Mg/L ? .57
Carbonate (CO3) in Mg/L ? .9
```

TOTAL DISSOLUED SOLIDS (TBS) IN Mg/L ? 646 Ph OF WATER SAMPLE ? 8.83\_


```
CONSTITUENTS
                                                                      IONS
                                                                                        z TDS
                                     Ma/L
                                                  Heq/L
Sodium (Na)
Potassium (K)
                                     249.9
                                                                   99
                                                                                        51.5
                                                  8.0<u>i</u>
                                                  П
                                                                           (Na + K)
                                    Í
                                    1.3
Calcium (Ca)
                                                                                         .5
                                                  4
Magnesium (Mg)
Total CATIONS (Mag/1)
Chloride (Cl)
Sulfate (804)
                                     .5
                                                  5
                                                                   . 3
                                                                                        (CA * MG)
                                                11.01114
                                                                                        3.1
                                    23.9
                                                  . 6
                                                                   6.6
                                                  Ø
                                                                                        Ø .
Bicarbonate (HCO3)
Carbonate (CO3)
                                    576.9
                                                  9.480001
                                                                   93.1
                                                                                        44.6
                                                  Ø
                                                                         <HCO3 +</pre>
    Total ANIONS (Meg/1):
                                                10.14972
                                 REPRESENTATIVE VALUES ______ SODIUM ADSORPTION RATIO:
HARDMESS:
                                     TOTAL DISSOLUED SOLIDS: WATER TYPE:
                    8.83
55 ×
SAMPLE Ph:
                                                                             646
STAR DIAGRAM:
                                                                          SODIUM-BICARBOMATE
              APPROXIMATE LIKELIHOOD OF BRINE CONTAMINATION VEAR DIAGRAM:
UERY UNLIKELY UERY UNLIKELY UERY UNLIKELY UERY UNLIKELY UERY UNLIKELY
     TRILINEAR DIAGRAM:
     STAR DIAGRAM:
     CHLORIDE/SODIUM RATIO:
                                                      POSSIBLE AND LIKELY
VERY UNLIKELY
     CHLORIDE/SULFATE RATIO:
     CHLORIDE CONCENTRATION:
```


#### IONIC RATIOS

RATIO:	MG/L BASIS:	MEG/L BASIS:
CHLORIDE/SODIUM	.92	.86
CHLORIDE/SULFATE	32	43.33
CHLORIDE/CALCIUM	18.18	10,27
CHLORIDE/MAGNESIUM	<sup>-^</sup> 45.19	15.49
Calcium/Magnesium	2 48	1.5
CHECTONYMANESION	2,79	3. 4.3

#### PROBABLE MINERAL COMPOSITION

.5 x	3.2 MG/L	CALCIUM BICARBONATE
94.8 %	496.3 MG/I	SODIUM BICARBONATE
.3 ×	1.8 MG/L	Magnesium bicarbonate
6.1 %	39.5 MG/L	sodium chloride
.1 %	1 116/L	SODIUM SULFATE
-3,48 ×	ION CHARGE	inbalance





	WellsCont
٠,	Selected
	Prom
	Vater
	ö
	Ana yses
-	Table 4 Chemical

[ <del>                                     </del>																		~~~							····		 		 		
Residual sodium carbon-		0.0	÷	: ~	9		}	. c	•	ָרָרָרָרָרָרָרָרָרָרָרָרָרָרָרָרָרָרָר	•	:	-1	*	٥.	7.	÷				<u>.                                    </u>						 				
Sodium adeorp- tion ratio	(perc)	0	; -	: :					, ,,	; ;	:		2.1	-1	Υ,		3.			,				-			 				
Per- cenc sod- fun		٠ -	8 8	, <b>2</b>	50		· <u>•</u>		, «	2		ዩ :	# !	c,	a	20.7	25										•		-		<del></del>
HZ.	1	٠.٠	7.37	7.7	7.2	2.0	7.7	2.8	7.8	<u> </u>	,	: ;	; ;		O	2	7.8			•									 		
Specific conduct- ance (micrombo		5 3	35	\$64	200	531	\$0¢	1,510	280	950	907	:	2 6	9	575	380	210			•							 ****	•			
Total hard-		, A	\$22	216	299	162	275	630	303	8	202		2 0	ç	292	526	213				-										
Dis- molved	,	i ž	K	338	7.56	¥	351	986	353	394	340		7	;	â	349	305								· ,			-			
Boron (B)	,		:		6.3		- 1	٠.,	:	•	:	:			:	;	:												 ·		
Hr. Gross	2	- 0	5.8	5.3	34.0	13.0	3.8	ď	4	e.					<u>.</u>	1.2	4										 		 		
Pluo- ride (F)	. 0	} ;	······································	~	7	:	:	v **	٠.	3.2	·		- 4		•	;	·:		<u></u>			-							•		
9 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	9	2	71	13	ĸ	13	12	202	2	**	-58		28		?	57	<b>e</b> 0											••			
Sul- fate (SO <sub>4</sub> )	0,4	1	3	5.4	7.	29.	38	212	27	30		22	3	- 4	· ·	3	27	· .													-
Bicar- bonace (HCO <sub>3</sub> )	301	8	297	262	210	279	352	157	356	37.5	36	360	280			₹	562						·	<del></del>			 				
Potas- sium h		:		;	2.0	:		٠ <u>٠</u>	 ;			<u>.                                    </u>	;			 ;	;						•			-	 			. ,	
F 1 2	5	•	<b>3</b>	1,	*	13	53	112	2	120	88	2	5	22			<del></del>			7				**********			 				
Magne- stum (Mg)	.3	۲	12	92	21	===	28	. 15	<u>.</u>	2	30	18	11	٠	20	: :	<u></u>	·											 	•	_
Cal- n clus (Ca)	113	101	\$6	53	*	43	15	6.76	101	12	ę	7,	63	96	80	5	2 .										 		•		
Iron (Pe)	f.	0-01	;	;	∹.	œ.	:	;	٥.	4	:	·	:	. 1	2.0									<del></del>			 			,	
5111ca (\$10 <sub>2</sub> )	;	9	é	₽	72	828	<u>*</u>	<b>:</b>	91	3	;	;	90	77	61		9						·····	-	-				 	<del></del>	$\dashv$
Date of S collection	Nov. 30, 1976	Mar. 7, 1950				Feb. 23, 1950		Feb. 4, 1975			Mar. 31, 1975	o o	June 30, 1971	Aug. 3, 1976	Mar. 6, 1950	Nar. 22, 1978									<u> </u>			<u>·</u>		···	
Depch of well or sampled interval (ft)	055	158										132		. 05	200	300											 _		 		
Aquifer	. Kr.pa	N. Pa	Kepa	a .	9 1	Xct B		₹ :	Keta	đ.	a a	Ketm	Keta	VCP4	ar F	Kepa											J.				
¥e11	UP-32-20-407	805	109	10: 3:	107-57	, i	ğ ë	2000	101-97	167	505	3	69	27-401	28-206	104	•						•	••					 		
			-																								 		 		1

VICTOR G. CARRILLO, CHAIRMAN ELIZABETH A. JONES, COMMISSIONER MICHAEL L. WILLIAMS, COMMISSIONER



RAMON FERNANDEZ JR., P.E.
DEPUTY DIRECTOR, OIL AND GAS DIVISION
D. W. -JOE- CRESS
DISTRICT DIRECTOR

## RAILROAD COMMISSION OF TEXAS

### OIL AND GAS DIVISION

November 5, 2010

Unidentified

#### STATUS REPORT

Lipsky, Steve Complaint No. 7B-9601 Lipsky Property Domestic Water Well Parker County, Texas Job No. 10-8443

Steve Lipsky's concern was natural gas in a water well. On October 14, 2010, a joint inspection of the Range Production Company, Butler Unit, Well No. 1H was conducted by Bubba Jonas, Richard Cortinas and Bobby Foust. On October 26, 2010, a joint inspection of the Lipsky water well and the neighboring Haley property water well was conducted by Bubba Jonas, Olin Macnamara, Steve Lipsky, Shyla Lipsky, Carl Willis, Chris Lister, Rick Haley and Sean Baker. On October 26, 2010, a joint inspection of the Range Production Company, Butler Unit, Well No. 1H and Teal Unit, Well No. 1H was conducted by Bubba Jonas, Olin Macnamara, Les Sahr, Sean Baker, Carl Willis and Chris Lister. During the inspections, the following were observed:

Oct. 14, 2010 Range Production Company conducted a production casing integrity test on the Butler Unit Lease (253732) Well No. 1H. The top of cement on the production casing is at 4,600 feet. A packer was set at 4,837 feet. The production casing held 845 psig for 30 minutes with 540 psig on the tubing. The bradenhead had 28 psig that remained consistent for the duration of the test. The Butler Unit, Well No. 1 was returned to production following the casing integrity test.

Oct. 26, 2010 Water and gas samples from the Lipsky property water well were collected by Carl Willis and Chris Lister from the Environmental Protection Agency for analysis. Sean Baker with Texas Fabco sampled gas from the Lipsky water well for analysis.

The Rick Haley property water well, adjoining the Lipsky property to the north, was inspected. The Haley water well is located at 175 Old Ranch Court (GPS coordinates N32.56505 W97.79401). The Haley water well was drilled in 2002, by Peck's Water Well Service. The well has a cement enclosure and lid. The water well is equipped with a down hole pump that supplies water to a treatment system inside a building behind the residence. The water treatment system consists of an ozonator, pressure and storage tanks, and a transfer pump that supplies water to the residence. Carl Willis and Chris Lister from the Environmental Protection Agency collected water samples for analysis from the water storage tank. A slight sulphur odor was noted in the water. Personnel monitors worn at the time of sampling did not register the presence of hydrogen sulfide gas.

Carl Willis and Chris Lister from the Environmental Protection Agency collected water and gas samples for analysis from the tubing string of the Range Production Company, Butler Unit, Well No. 1H. Sean Baker, Texas Fabco, collected gas samples from the tubing and bradenhead on the Butler Unit Well No. 1H.

Sean Baker collected gas samples from the production tubing of the Teal Unit, Well No. 1H and from the common injection flow line supplying gas to the lift system for both the Teal Unit and Butler Unit wells.

At the time of inspection, the Butler Unit, Well No. 1H was producing with 140 psig on the tubing, 680 psig on the casing and 32 psig on the bradenhead. The bradenhead valve was opened and the pressure was 0 psig within 10 seconds.

3444 NORTH 1<sup>67</sup> \* SUITE 600 \* ABILENE, TEXAS 79603 \* PHONE: 325/677-3545 \* 1
TDD 800/735-2989 OR TDY 512/463-7284 AN EQUAL OPPORTUNITY EMPLA

Range Resources Corp.
Docket: SDWA-06-2011-1208

Page 2 Lipsky, Steve Complaint 7B-9601 Unidentified Lipsky Property Parker County, Texas November 5, 2010

File review is scheduled for the week of December 6, 2010. Monthly inspections are scheduled to monitor the status of the Lipsky water well. Upon receipt and review of the analytical results further Commission action may be taken. Please direct any questions with regard to this complaint to Doug Allmand at (325) 677-3545.

Sincerely,

Doug Allmand Engineering Specialist

DA/mm

Assistant District Director

☐ District Director

cc: Field Operations, RRC, Austin

Steve Lipsky 127 River Oak Court Weatherford, TX 76087

Sid Slocum, Water Section Manager Texas Commission on Environmental Quality 2309 Gravel Drive Fort Worth, TX 76118

Ron VanWyk, Water Enforcement Branch Environmental Protection Agency 1445 Ross Avenue Dallas, TX 75202

Range Production Company (691703) 100 Throckmorton St Ste 1200 Fort Worth, TX 76102

Rick Haley 175 Old Ranch Court Weatherford, TX 76087 STATE OF TEXAS WELL REPORT for Tracking #108518

Owner:

Steve Lipiske

Owner Well #:

No Data

Address:

Silverado Addition Weatherford , TX 76086 Grid #:

32-26-6

Well Location:

Silverado Addition

Weatherford, TX 76086

Latitude:

32° 33' 43" N

Well County:

Parker

Longitude:

097° 46' 48" W

Elevation:

No Data

GPS Brand Used:

map

Type of Work:

New Well

Proposed Use:

Domestic

**Drilling Date:** 

Started: 4/11/2005

Completed: 4/11/2005

Diameter of Hole:

Diameter: 7 in From Surface To 200 ft

**Drilling Method:** 

Air Rotary

Borehole

Gravel Packed From: 60 ft to 200 ft

Completion:

Gravel Pack Size:

Annular Seal Data:

1st Interval: From 0 ft to 60 ft with 3 (#sacks and material)

2nd Interval: No Data 3rd Interval: No Data Method Used: Grout Cemented By: Larry Peck

Distance to Septic Field or other Concentrated Contamination: 150 ft

Distance to Property Line: No Data Method of Verification: Tape Approved by Variance: No Data

Surface Completion:

**Alternative Procedure Used** 

Water Level:

Static level: 65 ft. below land surface on 4/11/2005

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 180 ft

Well Tests:

Bailer

Yield: 18 GPM with 90 ft drawdown after 3 hours

Water Quality:

Type of Water: Good

Depth of Strata: No Data Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for

completion and resubmittal.

000437

Company Information: Peck's Water Well Service, Inc. 2650 White Settlement Road Weatherford, TX 76087

**Driller License** Number:

1598

Licensed Well

Larry Peck

**Driller Signature:** 

Registered Driller Apprentice Signature:

No Data

Apprentice

No Data

Registration Number:

Comments:

\$dfs

Surface Completion: Steel Sleeve

This well is located near the Parker/Hood County Line.

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner,

Please include the report's Tracking number (Tracking #108518) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

#### DESC. & COLOR OF FORMATION MATERIAL

CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description 0-3 Top Soil 3-18 Clay Gravel Sand Layers 18-35 Yellow Clay Sand 35-60 Green Shale with Rock 60-90 Shale with Sand 90-140 Green Shale Gravel Sand Lavers 140-145 Red Bed 145-190 Green Shale with Sand Layers 190-200 Red Bed

Dia. New/Used Type Setting From/To 4 New Plastic 0 180 4 New Plastic, Slotted 180 200 .020

Case 3:11-cv-00116-F Document 12-1 Filed 05/09/11 Page 56 of 73 PageID 279 Rick Hayley. 32.56505 -97.79041 ATTENTION OWNER: Confidentiality STATE OF TEXAS WATER WELL REPORT Privilege Notice on Reverse Side CITY: WEATHERFORD 1' OWNER: GODFREY, RODNEY ADDRESS: 175 OLD RANCE CT. STATE: TX ZIP: DRESS OF WELL: 5) GRID # 32-26-6 Junty: PARKER Street or RFD: SAME City, State, Zip code: SAME 4) PROPOSED USE: DOMESTIC 3) TYPE OF WORK: NEW WELL If Public Supply well, were plans submitted to the TNRCC? 6) WELL LOG: 09254 DIAMETER OF HOLE 7) DRILLING METHOD: 8) BORRHOLE COMPLETION: DIAMETER FROM TO DATE DRILLING: ٥ 220 AIR ROTARY GRAVEL PACKED 7 STARTED: 08/04/02 IF GRAVEL... FROM 100 FT. TO 220 COMPLETED: 08/04/02 FROM FT. TO CASING, BLANK PIPE, AND WELL SCREEN DATA: NEW/USED DESCRIPTION FROM TO GAGE CASING SCREEN 0 N PLASTIC 200 PLASTIC, SLOTTED 200 220 .020 9) CEMENTING DATA: GEOLOGICAL DESCRIPTION: Cemented from No. of Sacks Used 0 FT. TO 100 FT. FT. TO FT. FROM TO DESCRIPTION `. 0 16 TOP SOIL AND ROCK 35 GRAY SHALE AND ROCK Method used: GROUT 16 85 YELLOW CLAY ROCK 35 Cemented by: LARRY PECK 125 YELLOW GRAY SHALE ROCK 85 Distance to septic field lines: 160 SHALE COAL SAND LAYERS Method of verification of above distance: 125 No Septen when drilled 10) SURFACE COMPLETION: 160 195 GREEN SHALE GRAVEL SAND LAYERS 195 200 RED BED APP. ALTER, PROCD. Steel Sleeve 200 210 GREEN SHALE AND SAND LAYERS 210 220 RED BED 11) WATER LEVEL: STATIC LEVEL : 115 FT. DATE: 08/04/02 ARTESIAN FLOW: 12) PACKERS: TYPE DEPTH 13) TYPE PUMP: 14) WELL TEST: SUBMERSIBLE BAILER DEPTH TO PUMP: 200 YIELD: 12 GPM WITH & FT DRAWDOWN AFTER 3 HRS DEPTH OF STRATA: TYPE OF WATER: GOOD NO CHEMICAL ANALYSIS MADE

15) WATER QUALITY:

NO STRATA OF UNDESIRABLE WATER PENETRATED

COMPANY NAME: PECK'S WELL SERVICE INC.

WATER WELL DRILLER'S LICENSE NO.: 1598WPL ADDRESS: 2650 WHITE SETTLEMENT RD. CITY: WEATHERFORD

STATE: TX ZIP CODE: 76087

WELL NO. LOCATED ON MAP

FOR TWC USE ONLY

I HERBBY CERTIFY THAT THIS WELL WAS DRILLED BY ME (OR UNDER MY SUPERVISION) AND THAT EACH AND ALL OF THE STATEMENTS HEREIN ARE TRUE TO THE BEST OF MY KNOWLEDGE AND BELIEF. I UNDERSTAND THAT FAILURE TO COMPLETE ITEMS 1 THRU 15 WILL RESULT IN THE LOG(S) BEING RETURNED POR COMPLETION AND RESUBMITTAL.

028030

Beck arry (LICENSED WATER WELL DRILLER)

(REGISTERED DRILLER TRAINEE)

RECEIVED TOLR MAIL ROOM SEP 1 3 2002 AMOUNT RECEIPT #

## STATE OF TEXAS WELL REPORT for Tracking #226387

Owner:

Steve Hurst

Owner Well #:

Well Log 09541

Address:

Cactus Rio

Weatherford, TX 76086

Well Location:

Cactus Rio

Weatherford, TX 76086

Latitude:

Grid #:

32° 33' 49" N

32-26-5

Well County:

Parker

Longitude:

097° 47' 38" W

Elevation:

No Data

GPS Brand Used:

Map - address

Type of Work:

**New Well** 

Proposed Use:

**Domestic** 

**Drilling Date:** 

Started: 10/15/2005

Completed: 10/15/2005

Diameter of Hole:

Diameter: 7 in From Surface To 180 ft

**Drilling Method:** 

Air Rotary

Borehole

Gravel Packed From: 50 ft to 180 ft

Gravel Pack Size: Completion:

Annular Seal Data:

1st Interval: From 0 ft to 50 ft with 3 (#sacks and material)

2nd Interval: No Data 3rd Interval: No Data Method Used: Grout Cemented By: Larry Peck

Distance to Septic Field or other Concentrated Contamination: No Data

Distance to Property Line: No Data

Method of Verification: no septic when drilled

Approved by Variance: No Data

Surface

Completion:

Alternative Procedure Used

Water Level:

Static level: 75 ft. below land surface on 10/15/2005

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 160 ft

Well Tests:

Yield: 10 GPM with 60 ft drawdown after 2 hours

Water Quality:

Type of Water: Good Depth of Strata: No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data:

\$ \$ \$ \$ COC

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for

completion and resubmittal.

Company Information: Peck's Well Service Inc. 2650 White Settlement Rd. Weatherford, TX 76087

Driller License Number: 1598

Licensed Well Driller Signature:

Larry A. Peck

Registered Driller Apprentice No Data

Signature:

Apprentice Registration Number: No Data

Comments:

Surface Completion: Steel Sleeve Well has natural gas coming into well

at intermitting times.

\$mew

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #226387) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

#### DESC. & COLOR OF FORMATION MATERIAL

#### CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description 0 - 20 Red Yellow Clay

20 - 25 Green Clay Sand Layers

25 - 55 Green Clay Rock

**影点:33**000多

55 - 70 Green Shale with Sand Layers

70 - 140 Red Bed

140 - 145 Green Shale Gravel Sand Layers

145 - 160 Green Shale with Sandstone

160 - 180 Red Bed Yellow Clay

Dia. New/Used Type

Setting From/To

4 New Plastic 0 - 160

4 New Plastic, Slotted 160 - 180 .020

STATE OF TEXAS WELL REPORT for Tracking #226388

Owner:

Steve Hurst

Owner Well #:

Well Log 09542

Address:

Cactus Rio Ct.

Grid #:

32-26-5

Well Location:

Weatherford, TX 76086 Cactus Rio Ct. Weatherford, TX 76086

Latitude:

32° 33' 50" N

Well County:

Parker

Longitude:

097° 47' 41" W

Elevation:

No Data

GPS Brand Used:

Map - address

Type of Work:

**New Well** 

Proposed Use:

**Domestic** 

**Drilling Date:** 

Started: 10/17/2005

Completed: 10/17/2005

Diameter of Hole:

Diameter: 7 in From Surface To 120 ft

**Drilling Method:** 

Air Rotary

Borehole

Gravel Packed From: 40 ft to 120 ft

Completion:

**Gravel Pack Size:** 

Annular Seal Data:

1st Interval: From 0 ft to 40 ft with 3 (#sacks and material)

2nd Interval: No Data 3rd Interval: No Data Method Used: Grout Cemented By: Larry Peck

Distance to Septic Field or other Concentrated Contamination: 100 ft

Distance to Property Line: No Data Method of Verification: Taped Approved by Variance: No Data

Surface Completion: **Alternative Procedure Used** 

Water Level:

Static level: 50 ft. below land surface on 10/17/2005

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 100 ft

Well Tests:

Yield: 10 GPM with 60 ft drawdown after 2 hours

Water Quality:

Type of Water: Good Depth of Strata: No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data:

PALIBOA

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for

completion and resubmittal.

Company Information: Peck's Well Service Inc. 2650 White Settlement Rd. Weatherford, TX 76087

**Driller License** Number:

1598

Licensed Well

**Driller Signature:** 

Larry A. Peck

Registered Driller Apprentice Signature:

No Data

Apprentice Registration

No Data

Number: Comments:

**Surface Completion: Steel Sleeve** 

\$mew

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #226388) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

#### DESC. & COLOR OF FORMATION MATERIAL

CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description

0 - 20 Yellow Green Clay 20 - 30 Red Sand Clay

30 - 50 Green Shale and Rock

50 - 65 Green Shale with Sand Layers

65 - 66 Red Bed

66 - 80 Green Shale and Sand

80 - 110 Green and Gravel

110 - 120 Red Bed

Dia. New/Used Type

Setting From/To

4 New Plastic 0 - 100

4 New Plastic, Slotted 100 - 120 .020

STATE OF TEXAS WELL REPORT for Tracking #167075

Owner:

**STEVE HURST** 

Owner Well #:

No Data

Address:

2411 CACTUS RIO LN.

Grid #:

32-26-5

Well Location:

WEATHERFORD, TX 76087

Latitude:

32° 33' 44" N

Well County:

No Data Parker

Longitude:

097° 47' 45" W

Elevation:

No Data

GPS Brand Used:

GARMIN

Type of Work:

New Well

Proposed Use:

Domestic

**Drilling Date:** 

Started: 1/22/2009

Completed: 1/22/2009

Diameter of Hole:

Diameter: 7-7/8 in From Surface To 120 ft

**Drilling Method:** 

Air Rotary

Borehole

Gravel Packed From: 45 ft to 120 ft

Completion:

Gravel Pack Size:

Annular Seal Data:

1st Interval: From 0 ft to 45 ft with 15 (#sacks and material)

2nd Interval: No Data 3rd Interval: No Data

Method Used: CONVENTIONAL

Cemented By: No Data

Distance to Septic Field or other Concentrated Contamination: No Data

Distance to Property Line: 67 ft Method of Verification: MEASURED Approved by Variance: No Data

Surface

Completion:

Surface Sleeve Installed

Water Level:

Static level: 45 ft. below land surface on 1/22/2009

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 60 ft

Well Tests:

**Estimated** 

Yield: 20 GPM with 5 ft drawdown after .25 hour

Water Quality:

Type of Water: No Data

Depth of Strata: No Data

Chemical Analysis Made: No Data

Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data:

 $MP_{2}GGG$ 

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for

completion and resubmittal.

Company

BENNETT WATER WELL DRILLING, INC.

Information:

7300 W. HWY 377 TOLAR, TX 76476

**Driller License** 

4805

Number:

**JEFF BENNETT** 

Licensed Well

Driller Signature:

Registered Driller Apprentice Signature:

No Data

Apprentice Registration No Data

Number:

Comments:

No Data

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #167075) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

#### DESC. & COLOR OF FORMATION MATERIAL

CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description 0 - 45 CLAY 45 - 110 SAND 110 - 120 CLAY RED

Dia. New/Used Type 4 NEW PLASTIC 0 - 80 4 NEW SCREEN 80 - 120 .020 Setting From/To

Case 3:11-cv-00116-F Document 12-1 Filed 05/09/11 Page 63 of 73 PageID 286

Inventory No.: OS
Scan Code: 36

	X_PHONE CALLDISCUSSION FIELD TRIP CONFERENCEOTHER (Record of Item checked above)								
TO: Doug Almond (325-677-3545)	FROM: Ron Van Wyk	<u>DATE:</u> 8/17/10							
		<u>TIME:</u> 2:15pm							
Subject: Lipsky complain	nt								

Summary: Mr. Almond had been investigating Mr. Lipsky's complaint of gas in his water well. He was in the process of sending samples to the lab for analyses for anions/cations, BTEX, TPH. He had taken an earlier sample, but the temperature was out of range so the sample could not be analyzed. He had found that the nearest gas well is about a half mile away. However, it terminates near the Lipsky property. The Lipsky water well was drilled in 2005 by Peck Well Service. It is about 200 feet deep and constructed with PVC pipe. Water pumps from the well to an open storage tank in the garage and is treated due to high sulfur content. Gas was discovered in the Lipsky well when the well pump was pulled for repairs. The gas well was drilled about a year ago. Mr. Almond saw no problem with the gas well, other than some pressure build-up. Gas production is about 7000 feet deep. There is a possibility of shallow natural gas in the area. Mr. Almond plans to sample both the Lipsky well and the gas production well to do fingerprint analyses for comparison.

Mr. Lipsky has hired an environmental consultant, Wolf Eagle, who is sampling the well.

I gave Mr. Almond my phone number and address and asked him to call when he had more information.

## Conclusions/Actions Taken or Required:

Several wells in area. No neighbors have complained.

000710

Range Resources Corp.

Docket: SDWA-06-2011-1208

RECORD OF	X_PHONE CALL DISCUSSION FIELD TRIP CONFERENCE OTHER										
COMMUNICATION	(Record of Item checked above)										
TO: Ron Van Wyk	FROM: Steve Lipsky	<u>DATE:</u> 8/19/10									
		<u>TIME:</u> 10:30 am									
Subject: Gas in Water W	ell										

#### Summary:

He said that he had gas in his water well. Well is about 6 years old and first noticed problem a couple months ago. Two or three weeks ago he got the water well driller out who opened the well and found gas pressure. He says that the water now is cloudy (looks like alka seltzer) when it first flows from faucet. He said that a water hose connected to the well vent would shoot flames 6 feet. He knows of no neighbors with similar problems. He has a portable gas tester from the propane company and has some gas at his former residence a couple hundred yards away. He water use is mainly for his house hold (5 members). Lawn watering is from the river on his property. His lot is 14 acres. The average lot size is about 5 acres. He has a propane tank for cooking. The tank is maintaining pressure. He sent a sample to a lab and they said the gas was "off the charts". I asked him to send analytical results to both the Commission and EPA when he get them (7-10 days).

I told him that we would be monitoring the Railroad Commission investigation, but that the EPA would not get involved unless we had some reason to believe the Railroad Commission needed assistance. He was skeptical of the Railroad Commission's neutrality.

### Conclusions/Actions Taken or Required:



Complaint Call from Alisa Rich concerning gas in water well in Parker County Willie Lane to: Stephen Gilrein, Jerry Saunders, David Garcia 08/20/2010 03:37 PM

Cc: Debra Griffin, Diane Taheri, Carol Peters

Bcc: Esteban Herrera

On Friday, August 20, 2010, I received a call from Alisa Rich with Wolf-Eagle Environmental Services. Mr Steven Lipsky had obtained her company to collect water and air samples from his well. Ms. Rich was very concerned when she talked to me about the ongoing risk to Mr. Lipsky and his family. She relayed to me that one of her sampling techs had suffered respiratory distress after breathing what she believes may have been H2S fumes while sampling his well. Mr. Lipsky supposedly demonstrated in her presence that he could light his water hose which was attached to his well vent and that a "10-foot flare" was the result. She staid that she had a video of this and that she had sent it to the RA and that she would send me a copy. She told me that they had detected methane, ethane, propane and butane gases. She is to send me the data that she has collected from their preliminary assessment. I have not yet received this information or the video. She also said that the local Fire Marshall has been out to visit the location and that he was concerned, but I have no information concerning his assessment.

Mr. Lipsky's home is located in the Silverado on the Brazos development which is located near Weatherford, TX in Parker County. He moved there and his well was completed to 200 feet in 2005. We originally became aware of Mr. Lipsky's issues on August 10, 2010, when his initial complaint came in through Rob Lawrence. I called Mr. Lipsky personally and discussed his situation. He told me the RRC had been to his home and had collected a sample (we confirmed with the RRC that this was for analysis of anions/cations, BTEX and TPH). Ron Van Wyk of my staff subsequently contacted the RRC on August 17, 2010, to assess the RRC completed and proposed plans with respect to this complaint. The RRC representative told him that they had looked into the nearby well and had not noted any obvious concerns. The RRC also said that they would be collecting gas samples from the well production and Mr. Lipsky's well to do comparative fingerprint analyses.

There are several other water wells in the area, but to our knowledge no other neighbors have complained of well issues. Preliminary investigation by my staff has provided support to Mr. Lipsky's claim that Range Energy had completed a well approximately a half mile from his site. Records show that a horizontal frac line was drilled at approximately 5500 feet which underlies part of his property. I will have a team conduct a preliminary site investigation at Mr. Lipsky's property early next week. I have requested that a representative of the air inspections group also accompany my staff because of the air concerns.

Willie Lane Chief, Water Resources Section (6EN-WR) Water Enforcement Branch **EPA Region 6** Phone: 214.665.8460

Fax: 214.665.2168



Range Resources Corp. Docket: SDWA-06-2011-1208

# APPENDIX IN SUPPORT OF UNITED STATES' MEMORANDUM IN OPPOSITION TO DEFENDANTS' MOTION TO DISMISS

POST ADMINISTRATIVE RECORD DOCUMENTS

## RAILROAD COMMISSION OF TEXAS OFFICE OF GENERAL COUNSEL

OIL AND GAS DOCKET NO. 7B-0268629

IN RE: CONSERVATION AND PREVENTION
OF WASTE OF CRUDE PETROLEUM
AND NATURAL GAS IN THE STATE
OF TEXAS

Austin, Texas
December 8, 2010

COMMISSION CALLED HEARING
TO CONSIDER WHETHER OPERATION OF THE
RANGE PRODUCTION COMPANY
BUTLER UNIT, WELL NO. 1H (RRC NO. 253732)
AND THE TEAL UNIT, WELL NO. 1H (RRC NO. 253779),
NEWARK, EAST (BARNETT SHALE) FIELD, HOOD COUNTY, TEXAS,
ARE CAUSING OR CONTRIBUTING TO CONTAMINATION
OF CERTAIN DOMESTIC WATER WELLS IN PARKER COUNTY, TEXAS

NOTICE IS HEREBY GIVEN to the public and to all interested persons that under the legal authority and jurisdiction of Title 3, Oil and Gas, Subtitles A, B, and C of the Texas Natural Resources Code, Chapters 26, 27 and 29 of the Texas Water Code, and TEX. GOV'T CODE ANN. art. §§ 2001 et seq. (2010), the RAILROAD COMMISSION OF TEXAS will hold a hearing on JANUARY 10, 2011, at 9:00 a.m. at the William B. Travis State Office Building, 1701 N. Congress Avenue, Austin, Texas. This hearing will be conducted in conformity with the TEX. GOV'T CODE ANN. §§ 2001 et seq. (2010). For room assignment, on the date of the hearing please check the bulletin board in the 1st Floor lobby. Persons planning to attend this hearing are urged to contact Docket Services Section (512) 463-6848 immediately prior to the hearing date to be sure that the hearing will proceed on the scheduled date.

This hearing is called at the request of the Field Operations Section of the Oil & Gas

Division of the Railroad Commission of Texas to consider whether the operation of the Range

Production Company Butler Unit, Well No. 1H (RRC No. 253732) and Teal Unit, Well No. 1H

OIL AND GAS DOCKET NO. 7B-0268629

PAGE 2

(RRC No. 253779), Newark, East (Barnett Shale) Field, Hood County, Texas, is causing or contributing to contamination of certain domestic water wells in Parker County, Texas, and/or whether there is an alternative cause or contributor to any such contamination.

Informal complaints filed with the Commission and Commission staff investigation have disclosed that contamination may have occurred in certain domestic water wells located in the area of the Range Production Company, Butler Unit, Well No. 1H (RRC No. 253732) and the Teal Unit, Well No. 1H (RRC No. 253779), more particularly the Lipsky Property Domestic Water Well in Parker County, and the Hailey Property Domestic Water Well in Parker County. No staff determination has yet been made as to the source of any such contamination.

At the hearing, the Commission will consider the extent and causation of, and responsibility for, any contamination that may have occurred, or which is likely to occur, in domestic water wells in the area of the Range Production Company Butler Unit, Well No. 1H (RRC No. 253732) and the Teal Unit, Well No. 1H (RRC No. 253779), and, more particularly, whether the operation of these wells has caused or contributed, or may cause or contribute, to any such contamination. The Commission may also consider whether there is any alternative cause or contributor to any contamination that may have occurred. The Commission will also consider what action should be taken by the Commission to ensure that any contamination that may have occurred in domestic water wells in the area of the referenced wells is properly remediated and to ensure that any future contamination is prevented.

OIL AND GAS DOCKET NO. 7B-0268629

PAGE 3

Range Production Company is directed to appear at the hearing and to present evidence on the issue of whether the Butler Unit, Well No. 1H (RRC No. 253732) and the Teal Unit, Well No. 1H (RRC No. 253779) are causing or contributing, and/or will cause or contribute, to contamination of domestic water wells in the area of these wells.

On December 7, 2010, the United States Environmental Protection Agency, Region VI issued an Emergency Administrative Order relating to the subject matter of this hearing. The Commission encourages the participation of EPA in this hearing and presentation by EPA of evidence in its possession supporting findings of fact and conclusions of law in the Emergency Administrative Order.

If you have questions regarding this proceeding, please contact Ramon Fernandez, at (512) 463-6827. If you have any questions regarding the hearing procedure, please contact the Railroad Commission, Office of General Counsel, at (512) 463-6848.

IF A CONTINUATION IS NECESSARY, this hearing will proceed at the William B. Travis State Office Building, Austin, Texas, and, to the extent possible, on subsequent working days. The room number and exact time of the continuation will be announced on the record in this proceeding and recorded with Docket Services, Office of General Counsel, Railroad Commission of Texas.

PURSUANT TO SAID HEARING, the Commission will enter such rules, regulations, and orders as in its judgment the evidence presented may justify.

ANY REQUEST FOR POSTPONEMENT of this hearing must be received no later than five (5) working days prior to the scheduled date shown above. Copies of such request must be forwarded to all parties shown on the service list.

OIL AND GAS DOCKET NO. 7B-0268629

PAGE 4

TO APPEAR IN SUPPORT OF OR IN OPPOSITION TO THIS PROCEEDING, a party other than the applicant must file a notice of intent to appear with Docket Services, Office of General Counsel, at least five (5) working days in advance of the hearing date. A copy of the notice of intent to appear should be served on parties of record.

IF ANY PARTY DESIRES A WRITTEN TRANSCRIPT of the hearing by a Court Reporter, that party should notify Docket Services at (512) 463-6848, at least five (5) working days in advance of the hearing date. If a written transcript is requested, the Commission may assess the cost of the transcript to one or more parties. Unless any party requests a written transcript, the record will be made by audio recording.

ANY INDIVIDUAL WITH A DISABILITY who needs auxiliary aids and services in order to have an equal opportunity to effectively communicate and participate in this hearing must request such aids or services <u>at least</u> two weeks prior to the scheduled hearing by notifying the Personnel office of the Railroad Commission of Texas by mail at P.O. Box 12967, Austin, Texas 78711-2967, or by telephone at (512) 463-7327 or TDD No. (512) 463-7284.

ALL EXHIBITS FILED AS A PART OF THE RECORD in this cause must be submitted in duplicate. Data in Commission records may be incorporated by reference, but the reference must be specific, and if it includes exhibits filed in prior proceedings before the Commission, a copy of such exhibit properly identified shall be submitted for this record.

#### **CERTIFICATE OF SERVICE**

I hereby certify that a true and correct copy of the foregoing Notice of Hearing in Oil & Gas Docket No. <u>7B-0268629</u> was served on each of the persons named below by depositing same in the United States Mail (or by Inter-Agency Mail), postage thereon fully prepaid, properly addressed, as follows:

RANGE PRODUCTION COMPANY 100 THROCKMORTON STREET SUITE 1200 FORT WORTH TX 76102

RANGE PRODUCTION COMPANY ATTN: MIKE MIDDLEBROOK VICE PRESIDENT OF OPERATIONS 100 THROCKMORTON STREET SUITE 1200 FORT WORTH TX 76102

U S EPA REGION VI OFFICE OF REGIONAL COUNSEL (6RC-EW) ATTN: TUCKER HENSON 1445 ROSS AVENUE SUITE 1200 DALLAS TX 75202

U S EPA REGION VI OFFICE OF COMPLIANCE ASSURANCE AND ENFORCEMENT (6EN) ATTN: JOHN BLEVINS 1445 ROSS AVENUE SUITE 1200 DALLAS TX 75202

U S EPA REGION VI DR ALFREDO ALMENDARIZ REGIONAL ADMINISTRATOR 1445 ROSS AVENUE SUITE 1200 DALLAS TX 75202

STEVE LIPSKY 127 RIVER OAK COURT WEATHERFORD TX 76084

RICK HAILEY 175 OLD RANCH COURT WEATHERFORD TX 76084 JOHN TINTERA
EXECUTIVE DIRECTOR
RRC-AUSTIN

RAMON FERNANDEZ JR.
ACTING DEPUTY DIRECTOR
OIL AND GAS DIVISION
RRC - AUSTIN

STAFF ATTORNEY DAVID COONEY RRC - AUSTIN

JOE CRESS DISTRICT OFFICE 7B ABILENE -RRC

BILL MIERTSCHIN
OIL AND GAS DIVISION
RRC-AUSTIN

KEITH BARTON FIELD OPERATIONS RRC-AUSTIN

On this the <u>9th</u> day of <u>December</u>, 2010.

## DOLORES HOWARD

Office of General Counsel, RAILROAD COMMISSION OF TEXAS

From: "Riley, John" [jriley@velaw.com]
Sent: 12/09/2010 05:45 PM CST

To: Suzanne Murray Cc: Scott McDonald Subject: Range Resources

#### Suzanne:

Range's foremost concern is the safety and welfare of those around its operations and it is Range's highest priority to make sure that we address safety and welfare concerns first, before and above all other issues. Whether Range proves to be the cause of the concern is a question that can and will be answered later but, for now, let us unambiguously state that we will install gas monitors in the residences of concern. Indeed, this afternoon, Range installed a gas monitor in one residence and, at the other property owners' request, will install a gas monitor in their residence on Saturday. Further, one domestic well has not been used as a source of water since the September timeframe and, it is my understanding, that the other resident's own testing performed of his well performed in August did not indicate that it was affected. Regardless and to the point, Range has offered to provide potable water to these two families.

Range could not agree with EPA more that time is critical in these circumstances and, indeed, that is why Range has been actively engaged in investigating and addressing the issue for months. As expressed previously, we are more than willing to continue a transparent effort to address this situation as we have with the RRC and, to that end, we will continue to voluntarily cooperate with EPA. We will share information and offer subject matter experts as we go forward and address all concerns.

While we dispute EPA's factual or legal basis for the order, we have effectively complied with the provisions in EPA's order directed to ensure the immediate safety and welfare of the individuals affected. To the extent that you have called for another clear response as to whether we will adhere exactly to the remaining requirements of the order, we must respectfully state that we dispute the validity of the order and cannot agree to follow the precise ordering provisions found in Paragraph 50 A) - F).

I hope that this message removes any remaining uncertainty regarding Range's position at this point. We continue to look forward to the receipt of EPA's technical back-up for its order and our meeting next week. We also look forward to EPA's participation in the Texas Railroad Commission hearing in this matter, now scheduled for January 10, 2011.

Regards,

## John A. Riley

Partner
Vinson & Elkins LLP
2801 Via Fortuna, Suite 100
Austin, TX 78746-7568
Tel 512.542.8520
Fax 512.236.3329

Treasury Circular 230 Disclosure: To the extent this communication contains any statement regarding federal taxes.

that statement was not written or intended to be used, and it cannot be used, by any person (i) as a basis for avoiding

federal tax penalties that may be imposed on that person, or (ii) to promote, market or recommend to another party

any transaction or matter addressed herein.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. This email is

intended to be reviewed by only the individual or organization named above. If you are not the intended recipient or an

authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying

of this email and its attachments, if any, or the information contained herein is prohibited. If you have received this

email in error, please immediately notify the sender by return email and delete this email from your system.

Solicitors and Registered Foreign Lawyers. A list of partner names is available for inspection at CityPoint, One Ropemaker Street, London EC2Y 9UE. Vinson & Elkins RLLP is a limited liability partnership formed under the laws of New York and regulated by the Solicitors Regulation Authority (No. 00079019).

Thank You.